

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:
05/22/2013

Document Number:
667601356

Overall Inspection:
Unsatisfactory

FIELD INSPECTION FORM

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------|--------------------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | <input type="checkbox"/> |
| | 246549 | 327226 | HICKEY, MIKE | 2A Doc Num: | |

Operator Information:

OGCC Operator Number: 47120 Name of Operator: KERR-MCGEE OIL & GAS ONSHORE LP
 Address: P O BOX 173779
 City: DENVER State: CO Zip: 80217-

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|--------------|--------------------------------|---------|
| Cocciolone, Ashley | 720-929-6625 | Ashley.Cocciolone@anadarko.com | |
| Avant, Paul | 720-929-6457 | Paul.Avant@anadarko.com | |

Compliance Summary:

QtrQtr: NWSE Sec: 24 Twp: 3N Range: 66W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 07/20/2007 | 200115130 | PR | PR | S | | P | N |
| 12/27/2005 | 200083498 | PR | PR | S | | P | N |
| 10/28/1996 | 500170947 | PR | PR | | | P | N |

Inspector Comment:

Regular inspection of API #05-123-14346, HSR-Tuck #10-24. Workover rig anchor marker due West of the wellhead is no taller than the grass surrounding it.

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------------------------------|
| 246549 | WELL | PR | 12/01/2004 | GW | 123-14346 | HSR-TUCK 10-24 | <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Signs/Marker:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|----------------------|-----------------------------|---------|-------------------|---------|
| TANK LABELS/PLACARDS | Satisfactory | | | |

Inspector Name: HICKEY, MIKE

| | | | | |
|----------|--------------|--|--|--|
| BATTERY | Satisfactory | | | |
| WELLHEAD | Satisfactory | | | |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|--|------|--------|-------------------|---------|
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

Fencing:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|--------------|-----------------------------|---------|-------------------|---------|
| SEPARATOR | Satisfactory | | | |
| TANK BATTERY | Satisfactory | | | |

Equipment:

| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|-----------------------------|---|-----------------------------|---------|-------------------|---------|
| Bird Protectors | 1 | Satisfactory | | | |
| Gas Meter Run | 2 | Satisfactory | | | |
| Horizontal Heated Separator | 1 | Satisfactory | | | |
| Plunger Lift | 1 | Satisfactory | | | |

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS | |
|---------------------|----------------|----------|----------------|------------------|--|
| PRODUCED WATER | 1 | 100 BBLs | PBV FIBERGLASS | , | |
| S/U/V: Satisfactory | Comment: _____ | | | | |
| Corrective Action: | | | | Corrective Date: | |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|-------------------|----------|---------------------|---------------------|-----------------|--|
| | | | | | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |

| | | | | | |
|--------------------|-----------------------------|-----------------------------------|---------------------|----------------------|--|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | | |
| Contents | # | Capacity | Type | SE GPS | |
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | 40.206670,104.724910 | |
| S/U/V: | Satisfactory | Comment: | | | |
| Corrective Action: | | | | Corrective Date: | |
| Paint | | | | | |
| Condition | Adequate | | | | |
| Other (Content) | _____ | | | | |
| Other (Capacity) | _____ | | | | |
| Other (Type) | _____ | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |
| Venting: | | | | | |
| Yes/No | Comment | | | | |
| NO | | | | | |
| Flaring: | | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date | |
| | | | | | |

Predrill

Location ID: 327226

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

| Erosion BMPs | Present | Other BMPs | Present |
|--------------|---------|------------|---------|
| | | | |

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 246549 Type: WELL API Number: 123-14346 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____
 Comment: _____

- 1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
- Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
- Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
- Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
- Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
- Guy line anchors marked? Fail CM _____
 CA Remove or adequately mark guy line anchors. CA Date 07/01/2013

1003b. Area no longer in use? Pass Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Inspector Name: HICKEY, MIKE

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Seeding | Pass | Compaction | Pass | | | |

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____