


| | | | | | | |
|--|---|--|----|----|----|----|
| FORM INSP <small>Rev 05/11</small> | State of Colorado Oil and Gas Conservation Commission <small>1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109</small> |  | DE | ET | OE | ES |
|--|---|--|----|----|----|----|

FIELD INSPECTION FORM

| | | | | | |
|---------------------|-----------------------|------------------|--------------------------------|---|-------------------|
| Location Identifier | Facility ID 253635 | Loc ID 303812 | Inspector Name: SCHURE, KYM | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ |
|---------------------|-----------------------|------------------|--------------------------------|---|-------------------|

Inspection Date:
05/28/2013

Document Number:
664001027

Overall Inspection:
Unsatisfactory

Operator Information:

OGCC Operator Number: 10275 Name of Operator: AUGUSTUS ENERGY PARTNERS LLC

Address: 2016 GRAND AVE STE A

City: BILLINGS State: MT Zip: 59102

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|---------------------------|---------|
| Davis, Loni | 970-332-3585 | ldavis@augustusenergy.com | |

Compliance Summary:

QtrQtr: SENE Sec: 22 Twp: 4N Range: 47W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 06/27/2012 | 663300235 | PR | PR | U | | | N |
| 06/10/2011 | 200312358 | PR | PR | S | | | N |
| 12/10/1997 | 500180100 | PR | PR | | | P | N |
| 10/02/1995 | 500180099 | PR | PR | | | F | Y |

Inspector Comment:

Re-inspection on prior citation compliance. No containment under chemical additive tank has been installed. Condensate spill at wellhead.

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------------------------------|
| 253635 | WELL | PR | 06/16/1994 | GW | 125-07513 | WHITE STAR FARMS 5-22 | <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Signs/Marker:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|----------|-----------------------------|---------|-------------------|---------|
| WELLHEAD | Satisfactory | | | |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action:

| Good Housekeeping: | | | | |
|---------------------------|-----------------------------|---------------------------------|-------------------|------------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| DEBRIS | Unsatisfactory | Disconnected pipe at pump jack. | Remove debris. | 06/30/2013 |

| Spills: | | | | |
|----------------|----------|-----------|---|------------|
| Type | Area | Volume | Corrective action | CA Date |
| Condensate | WELLHEAD | <= 5 bbls | Remove/remediate stained soil at wellhead | 06/30/2013 |

Multiple Spills and Releases?

| Fencing/: | | | | |
|------------------|-----------------------------|--------------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| PUMP JACK | Satisfactory | Steel panels | | |

| Equipment: | | | | | |
|---------------------|---|-----------------------------|--|------------------------------------|------------|
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Ancillary equipment | 1 | Unsatisfactory | No containment under chemical additive tank. | Install containment or remove tank | 06/30/2013 |

| Venting: | |
|-----------------|---------|
| Yes/No | Comment |
| | |

| Flaring: | | | | |
|-----------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 303812

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

| Erosion BMPs | Present | Other BMPs | Present |
|--------------|---------|------------|---------|
| | | | |

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 253635 Type: WELL API Number: 125-07513 Status: PR Insp. Status: PR

Producing Well

Comment: Gas well, electric pump jack

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____
 Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: 05/28/2013

Land Use: _____

Comment: Footprint reduced

- 1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
- Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
- Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
- Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
- Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
- Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
 Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Inspector Name: SCHURE, KYM

Top soil replaced Pass Recontoured Pass Perennial forage re-established Pass

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment:

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | MHSP | Fail | |

S/U/V: Unsatisfactory Corrective Date: 06/30/2013

Comment: Cropland - No surface erosion from O&G operations observed. Chemical additive tank requires BMP's in place.

CA: Install BMP's for chemical additive tank.