

FORM INSP Rev 05/11	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		DE ET OE ES
-------------------------------	--	--	-------------

Inspection Date: 06/06/2013

Document Number: 663801093

Overall Inspection: **Unsatisfactory**

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
	<u>323996</u>	<u>323996</u>	<u>LONGWORTH, MIKE</u>		

Operator Information:

OGCC Operator Number: 96850 Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLC

Address: 1001 17TH STREET - SUITE #1200

City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Gardner, Michael	970/285-9377 ext. 2760	Michael.Gardner@WPXEnerg y.com	Principal Environmental Specialist
Moss, Brad	(970) 285-9377	Brad.Moss@WPXEnerg y.com	Production foreman

Compliance Summary:

QtrQtr: NENE Sec: 33 Twp: 6S Range: 94W

Inspector Comment:

Poly pipe, metalculvert, valves on location. Same as the last inspection doc # 661400009 with a corrective date of 01/02/2012. All pipe, and unused equipment must be removefrom the pad site. Lined dirt berm south of separator has oil stain. Remove unused equipment and pipping from berm and reclaim the berm. Send form 42 when corrective actions are complete by 06/14/2013.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
211442	WELL	PR	06/14/1998	OW	045-07202	QUARTER CIRCLE RANCH RMV 104-33	<input checked="" type="checkbox"/>
426327	TANK BATTERY	AC	04/14/2009		-	QUARTER CIRCLE RANCH- 66S94W 33NENE	<input type="checkbox"/>
426341	TANK BATTERY	AC	04/14/2009		-	QUARTER CIRCLE RANCH- 66S94W 33NENE	<input type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	Road needs to be bladed/maintained		

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
CONTAINERS	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			
BATTERY	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
UNUSED EQUIPMENT	Violation	Poly pipe, metalculvert, valves onlocation. Same as the last inspection doc # 661400009 with a corrective date of 01/02/2012	All pipe, and unused equipment must be removefrom the pad site. Send form 42 when corrective actions are complete.	06/14/2013
STORAGE OF SUPL	Satisfactory	United Rentals man lift parked on location. Needs to be moved off location.		
WEEDS	Satisfactory	Continue weed control		

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
SEPARATOR	Satisfactory			
TANK BATTERY	Satisfactory			

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Bird Protectors	2	Satisfactory			
Ancillary equipment	2	Satisfactory	2 totes chemicals 1 at well other at separator.		
Horizontal Heated Separator	1	Satisfactory			

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 323996

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 211442 Type: WELL API Number: 045-07202 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Fail CM _____
CA **All pipe, and unused equipment must be remove** CA Date **06/14/2013**

Waste Material Onsite? _____ CM _____
CA _____ CA Date _____

Unused or unneeded equipment onsite? Fail CM _____
CA **All pipe, and unused equipment must be remove** CA Date **06/14/2013**

Pit, cellars, rat holes and other bores closed? Pass CM _____
CA _____ CA Date _____

Guy line anchors removed? _____ CM _____
CA _____ CA Date _____

Guy line anchors marked? Pass CM _____
CA _____ CA Date _____

1003b. Area no longer in use? In Production areas stabilized? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment:

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Berms		MHSP	Pass	
Ditches		Culverts				
Seeding		Ditches	Fail			
Compaction		Compaction				

S/U/V: Corrective Date:

Comment:

CA:

COGCC Comments

Comment	User	Date
Poly pipe, metalculvert, valves on location. Same as the last inspection doc # 661400009 with a corrective date of 01/02/2012. All pipe, and unused equipment must be remove from the pad site. Lined dirt berm south of separator has oil stain. Remove unused equipment and pipping from berm and reclaim the berm. Send form 42 when corrective actions are complete by 06/14/2013.	longworm	06/06/2013