

FORM
INSPRev
05/11

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

06/13/2013

Document Number:

668600921

Overall Inspection:

Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	415370	415334	QUINT, CRAIG	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 100322 Name of Operator: NOBLE ENERGY INC

Address: 1625 BROADWAY STE 2200

City: DENVER

State: CO

Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Pavelka, Linda	303-228-4048	lpavelka@nobleenergyinc.com	
Ledet, Dave	970-848-0331 off	dledet@nobleenergyinc.com	

Compliance Summary:

QtrQtr: NWNW Sec: 36 Twp: 1S Range: 45W

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
415370	WELL	PR	06/16/2010	GW	125-11734	WITTE 11-36	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: 1	Wells: 1	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: 1
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: 1
Electric Generators: _____	Gas Pipeline: 1	Oil Pipeline: _____	Water Pipeline: 1
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	DIRT TRAIL THROUGH FARM GROUND		

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	SIGN BY WELL		
OTHER	Satisfactory	SIGN BY ENTRANCE		

Inspector Name: QUINT, CRAIG

Emergency Contact Number: (S/U/V) <u>Satisfactory</u>	Corrective Date: _____
Comment: _____	
Corrective Action: _____	

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	STEEL PANELS AROUND ALL EQUIPMENT		

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Ancillary equipment	2	Satisfactory	GAS SCRUBBER, TELEMETRY EQUIPMENT		
Vertical Separator	1	Satisfactory	VGS 50% BURIED		
Gas Meter Run	1	Satisfactory			
Pump Jack	1	Satisfactory	40 WEATHERFORD		
Prime Mover	1	Satisfactory	KOHLER COMMAND 18 GAS ENGINE		

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 415334

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____ **Date:** _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 415370 Type: WELL API Number: 125-11734 Status: PR Insp. Status: PR

Producing Well

Comment: PRODUCING

Environmental**Spills/Releases:**

Inspector Name: QUINT, CRAIG

Type of Spill: _____	Description: _____	Estimated Spill Volume: _____
Comment: _____		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	

Water Well:		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:	
Date Interim Reclamation Started: _____	Date Interim Reclamation Completed: _____
Land Use: DRY LAND	
Comment: _____	
1003a.	Debris removed? <u>Pass</u> CM _____
	CA _____ CA Date _____
	Waste Material Onsite? <u>Pass</u> CM _____
	CA _____ CA Date _____
	Unused or unneeded equipment onsite? <u>Pass</u> CM _____
	CA _____ CA Date _____
	Pit, cellars, rat holes and other bores closed? <u>Pass</u> CM _____
	CA _____ CA Date _____
	Guy line anchors removed? _____ CM _____
	CA _____ CA Date _____
	Guy line anchors marked? _____ CM _____
	CA _____ CA Date _____
1003b.	Area no longer in use? <u>Pass</u> Production areas stabilized ? <u>Pass</u>
1003c.	Compacted areas have been cross ripped? _____
1003d.	Drilling pit closed? <u>Pass</u> Subsidence over on drill pit? <u>Pass</u>
	Cuttings management: _____
1003e.	Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
	Production areas have been stabilized? <u>Pass</u> Segregated soils have been replaced? <u>Pass</u>
RESTORATION AND REVEGETATION	
<u>Cropland</u>	

Inspector Name: QUINT, CRAIG

Top soil replaced Pass

Recontoured Pass

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment: UNUSED AREAS OF THE LOCATION ARE FARMED. ACCESS AND LOCATION ARE FARMED OVER.

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: DRY LAND

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

S/U/V: Satisfactory Corrective Date: _____

Comment: ACCESS AND LOCATION ARE FARMED OVER.

CA: _____