

FORM INSP Rev 05/11	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		DE ET OE ES
-------------------------------	--	--	-------------

Inspection Date: 06/17/2013

Document Number: 670200577

Overall Inspection: Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID <u>293200</u>	Loc ID <u>335500</u>	Inspector Name: <u>BURGER, CRAIG</u>	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
---------------------	------------------------------	-------------------------	---	---	-------------------

Operator Information:

OGCC Operator Number: 10071 Name of Operator: BARRETT CORPORATION* BILL

Address: 1099 18TH ST STE 2300

City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, Aaron		aaxelson@billbarrettcorp.com	Production Foreman
Merry, Jesse		jmerry@billbarrettcorp.com	Area Superintendent
Kellerby, Shaun		Shaun.Kellerby@state.co.us	NW Field Supervisor

Compliance Summary:

QtrQtr: SWSW Sec: 26 Twp: 6S Range: 92W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/06/2013	670200418	PR	PR	U			N
06/09/2011	200312451	CO	PR	S			N
04/01/2009	200207767	CO	PR	S			N

Inspector Comment:

ECB off at time of inspection.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
293185	WELL	PR	09/18/2008	GW	045-14918	SCHIRER 13C-26-692	X
293186	WELL	PR	09/21/2008	GW	045-14919	SCHIRER 13B-26-692	X
293190	WELL	PR	09/15/2008	GW	045-14920	SCHIRER 13A-26-692	X
293192	WELL	PR	09/24/2008	GW	045-14921	SCHIRER 14B-26-692	X
293193	WELL	PR	11/12/2008	GW	045-14922	SCHIRER 14C-26-692	X
293196	WELL	PR	09/20/2008	GW	045-14923	SCHIRER 14D-26-692	X
293200	WELL	PR	09/23/2008	GW	045-14917	SCHIRER 13D-26-692	X

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:	
Yes/No	Comment
YES	Bolt on section of one gauge hatch at tank battery is bent and venting.

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Ignitor/Combustor	Unsatisfactory	Pilot light off.	Keep pilot light on.	07/05/2013

Predrill

Location ID: 335500

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 293185 Type: WELL API Number: 045-14918 Status: PR Insp. Status: PR

Facility ID: 293186 Type: WELL API Number: 045-14919 Status: PR Insp. Status: PR

Facility ID: 293190 Type: WELL API Number: 045-14920 Status: PR Insp. Status: PR

Facility ID:	293192	Type:	WELL	API Number:	045-14921	Status:	PR	Insp. Status:	PR
Facility ID:	293193	Type:	WELL	API Number:	045-14922	Status:	PR	Insp. Status:	PR
Facility ID:	293196	Type:	WELL	API Number:	045-14923	Status:	PR	Insp. Status:	PR
Facility ID:	293200	Type:	WELL	API Number:	045-14917	Status:	PR	Insp. Status:	PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): Y

Comment: _____

Pilot: OFF Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment:

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____