

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



|    |    |    |    |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:  
06/26/2013

Document Number:  
663801182

Overall Inspection:  
Satisfactory

**FIELD INSPECTION FORM**

|                     |               |               |                        |                    |                          |
|---------------------|---------------|---------------|------------------------|--------------------|--------------------------|
| Location Identifier | Facility ID   | Loc ID        | Inspector Name:        | On-Site Inspection | <input type="checkbox"/> |
|                     | <u>290544</u> | <u>335836</u> | <u>LONGWORTH, MIKE</u> | 2A Doc Num:        |                          |

**Operator Information:**

OGCC Operator Number: 10091 Name of Operator: BERRY PETROLEUM COMPANY  
 Address: 1999 BROADWAY STE 3700  
 City: DENVER State: CO Zip: 80202

**Contact Information:**

| Contact Name   | Phone        | Email       | Comment |
|----------------|--------------|-------------|---------|
| Johnson, Derek | 970-285-2200 | DSJ@Bry.com |         |

**Compliance Summary:**

QtrQtr: \_\_\_\_\_ Sec: \_\_\_\_\_ Twp: \_\_\_\_\_ Range: \_\_\_\_\_

**Inspector Comment:**

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name |                                     |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------------------------------|
| 289019      | WELL | PR     | 11/18/2010  | GW         | 045-13650 | LATHAM 29-27D | <input checked="" type="checkbox"/> |
| 289020      | WELL | PR     | 05/31/2012  | GW         | 045-13649 | LATHAM 29-18D | <input checked="" type="checkbox"/> |
| 289021      | WELL | IJ     | 08/13/2012  | DSPW       | 045-13648 | Latham 29-17D | <input checked="" type="checkbox"/> |
| 289022      | WELL | PR     | 05/31/2012  | GW         | 045-13647 | LATHAM 29-19D | <input checked="" type="checkbox"/> |
| 289023      | WELL | DA     | 09/03/2008  | LO         | 045-13646 | LATHAM 29-30D | <input checked="" type="checkbox"/> |
| 289024      | WELL | PR     | 11/03/2010  | GW         | 045-13645 | LATHAM 29-29D | <input checked="" type="checkbox"/> |
| 289025      | WELL | PR     | 11/18/2010  | GW         | 045-13644 | LATHAM 29-25D | <input checked="" type="checkbox"/> |
| 289026      | WELL | PR     | 11/03/2010  | GW         | 045-13643 | LATHAM 29-26D | <input checked="" type="checkbox"/> |
| 290544      | PIT  | AC     | 05/10/2007  |            | -         | LATHAM O-29   | <input type="checkbox"/>            |

**Equipment:**

Location Inventory

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

**Lease Road:**

| Type   | Satisfactory/Unsatisfactory | comment | Corrective Action | Date |
|--------|-----------------------------|---------|-------------------|------|
| Access | Satisfactory                |         |                   |      |

| <b>Signs/Marker:</b> |                             |         |                   |         |
|----------------------|-----------------------------|---------|-------------------|---------|
| Type                 | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| CONTAINERS           | Satisfactory                |         |                   |         |
| BATTERY              | Satisfactory                |         |                   |         |
| TANK LABELS/PLACARDS | Satisfactory                |         |                   |         |
| WELLHEAD             | Satisfactory                |         |                   |         |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

| <b>Spills:</b>   |      |        |                   |         |
|--|------|--------|-------------------|---------|
| Type   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

| <b>Fencing/:</b> |                             |         |                   |         |
|------------------|-----------------------------|---------|-------------------|---------|
| Type             | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD         | Satisfactory                |         |                   |         |
| PIT              | Satisfactory                |         |                   |         |

| <b>Venting:</b> |         |
|-----------------|---------|
| Yes/No          | Comment |
|                 |         |

| <b>Flaring:</b> |                             |         |                   |         |
|-----------------|-----------------------------|---------|-------------------|---------|
| Type            | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|                 |                             |         |                   |         |

**Predrill**

Location ID: 335836

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

| Erosion BMPs | Present | Other BMPs | Present |
|--------------|---------|------------|---------|
|              |         |            |         |

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_  
 Other BMPs: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
 Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
 Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 289019 Type: WELL API Number: 045-13650 Status: PR Insp. Status: PR

Facility ID: 289020 Type: WELL API Number: 045-13649 Status: PR Insp. Status: PR

Facility ID: 289021 Type: WELL API Number: 045-13648 Status: IJ Insp. Status: AC

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 289022 | Type: | WELL | API Number: | 045-13647 | Status: | PR | Insp. Status: | PR |
| Facility ID: | 289023 | Type: | WELL | API Number: | 045-13646 | Status: | DA | Insp. Status: | DA |
| Facility ID: | 289024 | Type: | WELL | API Number: | 045-13645 | Status: | PR | Insp. Status: | PR |
| Facility ID: | 289025 | Type: | WELL | API Number: | 045-13644 | Status: | PR | Insp. Status: | PR |
| Facility ID: | 289026 | Type: | WELL | API Number: | 045-13643 | Status: | PR | Insp. Status: | PR |

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment:

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment:

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_  
 Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Multi-Well Location

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

S/U/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**  
Pit Type: \_\_\_\_\_ Lined: YES Pit ID: \_\_\_\_\_ Lat: \_\_\_\_\_ Long: \_\_\_\_\_

**Lining:**  
Liner Type: Plastic Liner Condition: Adequate  
Comment: \_\_\_\_\_

**Fencing:**  
Fencing Type: Netting/Fen Fencing Condition: Adequate  
Comment: \_\_\_\_\_

**Netting:**  
Netting Type: Fence/Net Netting Condition: Good  
Comment: \_\_\_\_\_

Anchor Trench Present: YES Oil Accumulation: NO 2+ feet Freeboard: \_\_\_\_\_

Pit (S/U/V): Satisfactory Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

| Permit: | Facility ID | Permit Num | Expiration Date |
|---------|-------------|------------|-----------------|
|         | 290544      | 1433637    |                 |