

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

07/01/2013

Document Number:

670200614

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|---------------|---------------|----------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>211532</u> | <u>334859</u> | <u>BURGER, CRAIG</u> | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVERState: COZip: 80202-**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------------|-------|------------------------------|---------------------|
| Inspections, General | | cogcc.inspections@encana.com | |
| Kellerby, Shaun | | Shaun.Kellerby@state.co.us | NW Field Supervisor |

Compliance Summary:QtrQtr: SENW Sec: 33 Twp: 6S Range: 92W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 09/03/2007 | 200118372 | CO | PR | U | I | | N |
| 06/04/2007 | 200114365 | PR | PR | U | I | F | Y |
| 02/01/2007 | 200107492 | PR | PR | S | I | P | N |
| 05/30/2002 | 200036039 | PR | PR | S | | P | N |
| 02/03/1999 | 500143155 | PR | PR | | | P | N |

Inspector Comment:

Wells are reportedly shut in due to problem at the midstream compressor station. Major issues from previous investigation have been addressed.

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------------------------------|
| 211532 | WELL | PR | 07/15/1998 | GW | 045-07292 | BOULTON 33-6 | <input checked="" type="checkbox"/> |
| 261014 | WELL | PR | 01/16/2003 | GW | 045-07925 | SHIDELER 33-3A (F33) | <input checked="" type="checkbox"/> |
| 261015 | WELL | PR | 01/07/2003 | GW | 045-07926 | SHIDELER 33-3 (F33) | <input checked="" type="checkbox"/> |
| 261016 | WELL | PR | 01/12/2003 | GW | 045-07927 | BOULTON 33-6A (F33) | <input checked="" type="checkbox"/> |
| 263373 | WELL | PR | 01/21/2003 | GW | 045-08127 | SHIDELER 33-4C2 (F33) | <input checked="" type="checkbox"/> |

Equipment:**Location Inventory**

| | | | |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location**Signs/Marker:**

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|----------------------|-----------------------------|-------------------|------------------------------------------|------------|
| TANK LABELS/PLACARDS | Satisfactory | | | |
| BATTERY | Satisfactory | | | |
| WELLHEAD | Unsatisfactory | Inadequate signs. | Install signs to comply with rule 210.d. | 08/01/2013 |

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?**Equipment:**

| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|---------------------------|----|-----------------------------|-------------------|-------------------|---------|
| Vertical Heated Separator | 5 | Satisfactory | | | |
| Deadman # & Marked | 10 | Satisfactory | Some markers down | | |
| Gas Meter Run | 1 | Satisfactory | | | |
| Bird Protectors | 3 | Satisfactory | | | |
| Emission Control Device | 1 | Satisfactory | | | |
| Plunger Lift | 5 | Satisfactory | | | |

Facilities:☐ New Tank

Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|----------|---|----------|-----------|--------|
| METHANOL | 1 | 1000 GAL | STEEL AST | , |

S/U/V: Satisfactory Comment: same berm as condensate tanks

Corrective Action: _____

Corrective Date: _____

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

Corrective Action _____ Corrective Date _____

Comment _____

Inspector Name: BURGER, CRAIG

| | | | | |
|--------------------|--------------|-----------------------------------|------------------------------------|-----------------------|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS |
| PRODUCED WATER | 1 | 100 BBLS | STEEL AST | 37.484540,-107.675350 |
| S/U/V: | Satisfactory | Comment: | Used for blowing down bradenheads. | |
| Corrective Action: | | | | Corrective Date: |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| | | | | |
|-------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| | | | |
|-------------------|--|-----------------|--|
| Corrective Action | | Corrective Date | |
| Comment | | | |

| | | | | |
|--------------------|--------------|-----------------------------------|----------------|-----------------------|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS |
| CONDENSATE | 2 | 300 BBLS | STEEL AST | 39.484750,-107.675130 |
| S/U/V: | Satisfactory | Comment: | | |
| Corrective Action: | | | | Corrective Date: |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| | | | | |
|-------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| | | | |
|-------------------|--|-----------------|--|
| Corrective Action | | Corrective Date | |
| Comment | | | |

| | | |
|-----------------|---------|--|
| Venting: | | |
| Yes/No | Comment | |
| NO | | |

| | | | | |
|-------------------|-----------------------------|---------|-------------------|---------|
| Flaring: | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Ignitor/Combustor | Satisfactory | | | |

Predrill

Location ID: 334859

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 211532 Type: WELL API Number: 045-07292 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____
 S/V: Satisfactory CA Date: _____
 CA: _____
 Comment: _____

Facility ID: 261014 Type: WELL API Number: 045-07925 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____
 S/V: Satisfactory CA Date: _____
 CA: _____
 Comment: _____

Facility ID: 261015 Type: WELL API Number: 045-07926 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____
 S/V: Satisfactory CA Date: _____
 CA: _____
 Comment: _____

Facility ID: 261016 Type: WELL API Number: 045-07927 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____
 S/V: Satisfactory CA Date: _____
 CA: _____
 Comment: _____

Facility ID: 263373 Type: WELL API Number: 045-08127 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____
 S/V: Satisfactory CA Date: _____
 CA: _____
 Comment: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Complaint:

| Tracking Num | Category | Assigned To | Description | Incident Date |
|--------------|----------|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|
| 200118362 | ODOR | GRAHAM, DAVE | LINDA STATED THAT SHE HAS BEEN SMELLING A STRONG ODOR COMING FROM THE WEST FROM THE GAS FIELD. SHE STATED THAT THE WIND IS COMING FROM THE WEST AND THAT THE ODOR BAD. SHE STARTED NOTICING THE ODOR AGAIN ON 9-1-07 AND CALLED ENCANA TO TELL THEM OF THE ODOR PROBLEM. SHE CALLED ME ON 9-2-07, AND I WOULD GET BACK TO HER WITH THE RESULTS. | 09/02/2007 |

Emission Control Burner (ECB): Y _____

Comment: _____

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? Pass CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass1003c. Compacted areas have been cross ripped? Pass1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Inspector Name: BURGER, CRAIG

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | Ditches | Pass | | | |
| Ditches | Pass | Culverts | Pass | MHSP | Pass | |
| Waddles | Pass | Slope Roughening | Pass | | | |
| Slope Roughening | Pass | Tackifiers | Pass | | | |

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____