

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
07/02/2013

Document Number:
668300458

Overall Inspection:
Unsatisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	<u>201246</u>	<u>319746</u>	<u>JOHNSON, RANDELL</u>	2A Doc Num:	

Operator Information:

OGCC Operator Number: 100322 Name of Operator: NOBLE ENERGY INC
 Address: 1625 BROADWAY STE 2200
 City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Dumas, Ken	720-587-2150/34162	kdumas@nobleenergyinc.com	
Pavelka, Linda	970-304-5217	lpavelka@nobleenergyinc.com	
Bruner, Ryan	303-228-4158	rbruner@nobleenergyinc.com	

Compliance Summary:

QtrQtr: NENE Sec: 22 Twp: 1S Range: 65W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/15/2013	668300171	PR	SI	U	I		N
07/20/2000	895993	CO	PR	S		P	N
06/01/2000	895969	CO	PR	U		F	Y
11/30/1999	894227	PR	PR	U		F	Y

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
201246	WELL	PR	01/31/2008	OW	001-06649	SUTTON 41-22	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	Unsatisfactory	Steel production tank does not have the required contents signage	Install sign to comply with rule 210.d.	08/02/2013
BATTERY	Unsatisfactory	Battery does not have the required well name, well location, operator name or emergency contact number signage	Install sign to comply with rule 210.d.	08/02/2013
WELLHEAD	Unsatisfactory	Wellhead sign does not have the required operator name or emergency contact number	Install sign to comply with rule 210.d.	08/02/2013

Emergency Contact Number: (S/U/V) Unsatisfactory Corrective Date: 08/02/2013

Comment:

Corrective Action:

Spills:				
Type	Area	Volume	Corrective action	CA Date
Crude Oil	Tank	<= 5 bbls	Prevent further leaks at back of steel production tank/Remove or remediate contaminated soil	08/02/2013

Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK BATTERY	Satisfactory	Twisted wire fencing		
SEPARATOR	Satisfactory	Barbed wire fencing		
WELLHEAD	Satisfactory	Pipe fencing		
OTHER	Satisfactory	Pipe fencing around meter run		

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gas Meter Run	1	Satisfactory			
Bird Protectors	1	Satisfactory			
Horizontal Heated Separator	1	Satisfactory			
Plunger Lift	1	Satisfactory			

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
OTHER	1	300 BBLS	STEEL AST	39.954450,-104.643790	
S/U/V:	Comment:		Contents unknown - no signage		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	1	<100 BBLS		39.954450,-104.643790	
S/U/V:	Comment:		53 bbls - Located inside same berm as crude oil tank		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition					
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient		
Corrective Action				Corrective Date	
Comment					

Venting:		
Yes/No	Comment	
NO		

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 319746

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 201246 Type: WELL API Number: 001-06649 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

S/V: _____ CA Date: _____

CA: _____

Comment: Producing intermittently

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? Fail CM _____

CA Mark deadmen CA Date 08/02/2013

1003b. Area no longer in use? Pass

Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass
 Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Fail	Gravel	Fail			
Other	Fail	Other	Fail			Vegetation
Compaction	Fail	Compaction	Fail			

S/U/V: Unsatisfactory Corrective Date: 08/02/2013

Comment: Rutting and erosion on location and lease road

CA: Repair rutting and erosion/Establish best management erosion control practices at location and on lease road

COGCC Comments

Comment	User	Date
Reinspection - Last inspection 05/15/13 (Doc. #668300171) - Next inspection (3rd inspection) scheduled on or after the 2nd of August 2013	johnsonr	07/02/2013