

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

07/11/2013

Document Number:

671100202

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------|--|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | |
| | 279035 | 333241 | Peterson, Tom | 2A Doc Num: | |

Operator Information:OGCC Operator Number: 10110 Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1700 BROADWAY SUITE 650City: DENVER State: CO Zip: 80290**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|----------------------------|---------|
| Musgrave, Tim | (970) 768-6097 | tmusgrave@gwogco.com | |
| DERANLEAU, GREG | | greg.deranleau@state.co.us | |

Compliance Summary:QtrQtr: SWSE Sec: 26 Twp: 6N Range: 67W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 07/24/2007 | 200115474 | PR | PR | S | I | P | N |
| 12/07/2006 | 200101217 | SR | PR | S | I | P | N |
| 08/15/2006 | 200097577 | PR | PR | S | | P | N |
| 09/29/2005 | 200077630 | PR | WO | U | | P | N |
| 09/29/2005 | 200077896 | DG | DG | S | | P | N |
| 09/29/2005 | 200077899 | PR | WO | S | | P | N |

Inspector Comment:

Shared battery location with API# 123-26338, 123-26339See Facilities

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|---------------|---|
| 279033 | WELL | PR | 02/15/2009 | GW | 123-23135 | MERSHON 26-54 | X |
| 279035 | WELL | PR | 05/15/2006 | GW | 123-23134 | MERSHON 26-33 | X |
| 279036 | WELL | PR | 05/15/2006 | GW | 123-23133 | MERSHON 26-43 | X |

Equipment:Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Inspector Name: Peterson, Tom

| | | | | |
|----------------------|-----------------------------|---------|-------------------|---------|
| Signs/Marker: | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD | Satisfactory | | | |
| TANK LABELS/PLACARDS | Satisfactory | | | |
| BATTERY | Satisfactory | | | |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

| | | | | |
|--|------|--------|-------------------|---------|
| Spills: | | | | |
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| | | | | |
|------------------|-----------------------------|-----------|-------------------|---------|
| Fencing/: | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD | Satisfactory | Chainlink | | |

| | | | | | |
|-------------------|---|-----------------------------|---------|-------------------|---------|
| Equipment: | | | | | |
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Plunger Lift | 3 | Satisfactory | | | |
| Flow Line | 3 | Satisfactory | | | |

| | | | | | |
|---|---|----------|--|------------------|--|
| Facilities: <input type="checkbox"/> New Tank Tank ID: _____ | | | | | |
| Contents | # | Capacity | Type | SE GPS | |
| | | | | | |
| S/U/V: | | Comment: | Shared battery location with API# 123-26338, 123-26339 | | |
| Corrective Action: | | | | Corrective Date: | |

| | |
|------------------|--|
| Paint | |
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

| | | | | |
|-------------------|----------|---------------------|---------------------|-----------------|
| Berms | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

| | |
|-----------------|---------|
| Venting: | |
| Yes/No | Comment |
| NO | |

| | | | | |
|-----------------|-----------------------------|---------|-------------------|---------|
| Flaring: | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 333241

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 279033 Type: WELL API Number: 123-23135 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 279035 Type: WELL API Number: 123-23134 Status: PR Insp. Status: PR

Inspector Name: Peterson, Tom

Producing Well

Comment: PR

Facility ID: 279036 Type: WELL API Number: 123-23133 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

Lat Long

DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? Pass CM

CA CA Date

Waste Material Onsite? Pass CM

CA CA Date

Unused or unneeded equipment onsite? Pass CM

CA CA Date

Pit, cellars, rat holes and other bores closed? Pass CM

CA CA Date

Guy line anchors removed? Pass CM

CA CA Date

Guy line anchors marked? CM

CA CA Date

Inspector Name: Peterson, Tom

1003b. Area no longer in use? Pass Production areas stabilized ? Pass
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass
Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Pass Recontoured Pass Perennial forage re-established Pass

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | SI | Pass | |

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____

COGCC Comments

| Comment | User | Date | |
|--|----------|------------|--|
| Shared battery location with API# 123-26338, 123-26339 See Facilities | PetersoT | 07/11/2013 | |
| | | | |