

<b>FORM INSP</b> Rev 05/11	<b>State of Colorado</b> <b>Oil and Gas Conservation Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		DE ET OE ES
-------------------------------	--	--	-------------

Inspection Date: 07/12/2013

Document Number: 668601069

Overall Inspection: **Unsatisfactory**

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection <input type="checkbox"/>
	<u>208548</u>	<u>381181</u>	<u>QUINT, CRAIG</u>	2A Doc Num: _____

**Operator Information:**

OGCC Operator Number: 19170 Name of Operator: CONQUEST OIL COMPANY

Address: 8207 W 20TH STREET - SUITE B

City: GREELEY State: CO Zip: 80634

**Contact Information:**

Contact Name	Phone	Email	Comment
	970-356-5560	rae@conquestcompanies.com	

**Compliance Summary:**

QtrQtr: SESW Sec: 7 Twp: 12S Range: 50W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/18/2012	663900397	PR	PR	U	F		N
09/03/2010	200269753	PR	WO	U			Y
09/18/1996	500140859	SR	DA		P	P	N
07/21/1995	500140858	DG	ND			P	N

**Inspector Comment:**

---

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name
208548	WELL	PR	11/08/2010	OW	017-07483	HOUSE 24-7 #1 <input checked="" type="checkbox"/>

**Equipment:** Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>1</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>1</u>	Separators: <u>1</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: <u>1</u>
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: <u>1</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Unsatisfactory	DIRT ROAD THROUGH PASTURE WITH AREAS OF EROSION.	REPAIR AND INSTALL BMP'S	10/12/2013

<b>Signs/Marker:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	Satisfactory	STICKERS ON TANK		
BATTERY	Satisfactory	SIGN BY TANK		
OTHER	Satisfactory	LEASE SIGN AT LOCATION ENTRANCE.		

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
LOCATION	Satisfactory	LOCATION IS FENCED WITH WIRE.		

<b>Equipment:</b>					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Ancillary equipment	4	Unsatisfactory	PROPANE TANK, DAY TANK, 2-CHEMICAL TANKS WITHOUT CONTAINMENTS.	INSTALL BMP'S	10/12/2013
Prime Mover	1	Satisfactory	EA-30 AJAX GAS ENGINE.		
Pump Jack	1	Unsatisfactory	228 SMACO WITH WRIST PINS BROKE AND WALKING BEAM PEDISTAL BROKE. WALKING BEAM IS ON THE GROUND.	REPAIR UNIT OR REMOVE.	10/12/2013

<b>Facilities:</b>		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
CRUDE OIL	1	400 BBLS	STEEL AST	39.012180,-103.043480	
S/U/V:	Satisfactory	Comment: _____			
Corrective Action:	_____			Corrective Date:	_____
<b>Paint</b>					
Condition	Adequate				
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action	_____			Corrective Date	_____
Comment	_____				
<b>Venting:</b>					
Yes/No	Comment				_____
<b>Flaring:</b>					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

**Predrill**

Location ID: 381181

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

BMP Type	Comment
PROPOSED BMPs	Proposed BMP Plan
	Conquest Oil Company
	8207 West 20th Street
	Greeley, CO 80634
	c/o Ted Pagano
	970 -590 -3944 (Cell)
	303 -595 -1530 (Fax)

Stormwater Discharges Associated with Construction Oil and Gas Activity. Application has been filed with Colorado Department of Public Health and Environment Water Quality Control Division and is pending. Approved permit will be in place before any dirt work begins.

Re -Enter House 24 -7 # 1 well

T12S, R50W

Sec. 7: SE1/4SW1/4

Cheyenne County, Colorado

Description of Well Site and Construction Area

1 -3 acre site with access road for drilling of oil and gas well. Terrain is flat to rolling with native grass and sagebrush. No receiving waters will be affected by well pad. Drilling pits closed and reclaimed with the drillsite, reseeded within 6 months weather permitting. Silt fences will be installed on low side site of drill site. Topsoil will be separated and spread on drill site as final operation before reseeding operations. To prevent soil erosion site will be disked and straw crimped in.

Stormwater Management Plan (SWMP) is on file in Conquest Oil Company office.

Spill Prevention, Control and Countermeasure Plan is on file in Conquest Oil Company office.

Physical Address: 401 Arapahoe St.

id Mail to: Box 384 Kiowa, CO 80117

F; - n Sure CO. Ph. 303 -621 -8672 - Fax 303 -621 -2717

[www.highprairiesurvey.com](http://www.highprairiesurvey.com)

Job # 10026 -HOUSE 24 -7 #1 Inv # 1085

High Prairie Surveying of Kiowa, Colorado has in accordance with a request from Jack Fincham, Conquest Oil Company has determined the location of House 24 -7 #1 (a capped well casing) to be 900 feet FSL, and 2204 feet FWL, (90° off Section lines) of SECTION 7, Township 12s, Range 50w of the 6th Principal Meridian, Cheyenne County, Colorado.

Date: Staked on 2/25/2010 drawn on 3/1/2010. Re: Staked by Keith Westfall

Drawn: Drawn by Elijah Frane Topo Exhibit

**Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_

Other BMPs: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 208548 Type: WELL API Number: 017-07483 Status: PR Insp. Status: SI

**Producing Well**

Comment: WELL IS SHUT IN FROM PUMPING UNIT MECHANICAL FAILURE. WALKING BEAM IS ON THE GROUND. WITHIN 10 DAYS OF RECEIPT OF INSPECTION INFORM COGCC INSPECTOR OF A TIME FRAME FOR REPAIR OF UNIT OR SUBMIT A SUNDRY NOTICE FOR STATUS OF WELL AND M.I.T. WELL WITHIN 30 DAYS TO MAINTAIN SHUT IN STATUS.

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS: \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use: RANGELAND

Comment:

- 1003a. Debris removed? Pass CM CA Waste Material Onsite? Pass CM CA Unused or unneeded equipment onsite? Pass CM CA Pit, cellars, rat holes and other bores closed? Pass CM CA Guy line anchors removed? CM CA Guy line anchors marked? CM CA

1003b. Area no longer in use? Pass Production areas stabilized? Pass

1003c. Compacted areas have been cross ripped?

1003d. Drilling pit closed? Pass Subsidence over on drill pit?

Cuttings management:

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Recontoured Perennial forage re-established

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation In

1003 f. Weeds Noxious weeds? P

Comment: UNUSED AREAS OF THR LOCATION ARE IN PROCESS OF VEGETATION.

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Inspector Name: QUINT, CRAIG

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Fail	MHSP	Fail	

S/U/V: **Unsatisfactory** Corrective Date: **10/12/2013**

Comment: **DAY TANK AND CHEMICAL TANKS WITHOUT BMP's, AREAS OF EROSION ON ACCESS ROAD.**

CA: **INSTALL BMP'S**