

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

07/19/2013

Document Number:

663801302

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	334656	334656	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVERState: COZip: 80202-**Contact Information:**

Contact Name	Phone	Email	Comment
Insp., General	970-285-2665	cogcc.inspections@encana.com	
KELLERBY, SHAUN		shaun.kellerby@state.co.us	
AHLSTRAND, DENNIS		dennis.ahlstrand@state.co.us	

Compliance Summary:QtrQtr: NWSE Sec: 16 Twp: 7S Range: 95W**Inspector Comment:**

Add loc. id. 311686 and 324403 to this location id. 334656. 16-10 & 16-11 are on top of each other on GIS Map. 16-10BB is 350' east of where it should be on the map.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
287314	WELL	PR	08/30/2007	GW	045-12962	SHORE 16-10 (PJ16)	<input checked="" type="checkbox"/>
287994	WELL	PR	09/08/2007	GW	045-13126	SHORE 16-11BB(PJ16)	<input checked="" type="checkbox"/>
287995	WELL	PR	08/29/2007	GW	045-13125	SHORE FEDERAL 16-14 (PJ16)	<input checked="" type="checkbox"/>
287996	WELL	PR	08/30/2007	GW	045-13124	SHORE 16-11(PJ16)	<input checked="" type="checkbox"/>
288990	WELL	PR		GW	045-13628	SHORE 16-10BB (P116)	<input checked="" type="checkbox"/>
289666	WELL	PR	02/18/2010	GW	045-13846	SHORE FEDERAL 16-15BB (PJ16)	<input checked="" type="checkbox"/>
289667	WELL	PR		GW	045-13845	SHORE FEDERAL 16-15 (PJ16)	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	no legal discription		
BATTERY	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WEEDS	Satisfactory	Continue weed control		

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
LOCATION	Satisfactory			

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gas Meter Run	1	Satisfactory			
Plunger Lift	7	Satisfactory	Plugers need painted		
Horizontal Heated Separator	7	Satisfactory	1 quad 1 triple		
Bird Protectors	3	Satisfactory			

Inspector Name: LONGWORTH, MIKE

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
METHANOL	1	<50 BBLS	STEEL AST	,
S/U/V:	Satisfactory		Comment:	
Corrective Action:			Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action				Corrective Date	
-------------------	--	--	--	-----------------	--

Comment					
---------	--	--	--	--	--

Facilities:	<input type="checkbox"/> New Tank	Tank ID: _____
--------------------	-----------------------------------	----------------

Contents	#	Capacity	Type	SE GPS
CONDENSATE	4	300 BBLS	STEEL AST	39.435010,108.001600

S/U/V:	Satisfactory		Comment:	
--------	--------------	--	----------	--

Corrective Action:				Corrective Date:	
--------------------	--	--	--	------------------	--

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action				Corrective Date	
-------------------	--	--	--	-----------------	--

Comment					
---------	--	--	--	--	--

Venting:		
Yes/No	Comment	

Flaring:							
Type	Satisfactory/Unsatisfactory				Comment	Corrective Action	CA Date

Predrill

Location ID: 334656

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 287314 Type: WELL API Number: 045-12962 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well 39.43489 108.00138 Taken with Garmin nuvi

Facility ID: 287994 Type: WELL API Number: 045-13126 Status: PR Insp. Status: PR

Inspector Name: LONGWORTH, MIKE

Producing Well

Comment: Producing well 39.43473 108.137 Taken with Garmin nuvi

Facility ID: 287995 Type: WELL API Number: 045-13125 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well 39.43469 108.00137 Taken with Garmin nuvi

Facility ID: 287996 Type: WELL API Number: 045-13124 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well 39.43479 108.00138 Taken with Garmin nuvi

Facility ID: 288990 Type: WELL API Number: 045-13628 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well was added to this location. 39.43489 108.00138 Taken with Garmin nuvi

Facility ID: 289666 Type: WELL API Number: 045-13846 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well 39.43482 108.00124 Taken with Garmin nuvi

Facility ID: 289667 Type: WELL API Number: 045-13845 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well was added to this location 39.43479 108.00124 Taken with Garmin nuvi

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? Fail CM _____
 CA Mark or remove anchors CA Date 08/02/2013

1003b. Area no longer in use? In Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Inspector Name: LONGWORTH, MIKE

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass			
Gravel	Pass	Ditches	Pass			
Berms	Pass	Berms	Pass			
Compaction	Pass	Compaction	Pass			
Seeding		Gravel	Pass			

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
663801302	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3151086