


FORM INSP Rev 05/11	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109				DE	ET	OE	ES
	Inspection Date: <u>07/29/2013</u>							

FIELD INSPECTION FORM

Location Identifier	Facility ID <u>221342</u>	Loc ID <u>334263</u>	Inspector Name: <u>BURGER, CRAIG</u>	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
---------------------	------------------------------	-------------------------	---	---	-------------------

Document Number:
670200712

Overall Inspection:
Satisfactory

Operator Information:

OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INC

Address: 370 17TH ST STE 1700

City: DENVER State: CO Zip: 80202-

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, General		cogcc.inspections@encana.com	
Kellerby, Shaun		Shaun.Kellerby@state.co.us	NW Field Supervisor

Compliance Summary:

QtrQtr: SWNE Sec: 26 Twp: 8S Range: 91W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/05/2012	663800527	PR	PR	S	I		N
10/01/2002	200034523	PR	PR	S		P	N

Inspector Comment:

No sign of plugged and abandoned well 077-08589 in reclaimed area.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
221342	WELL	PR	06/28/1958	GW	077-05135	DIVIDE CREEK UNIT 2	X
221987	WELL	PA	09/28/2010	GW	077-08589	DIVIDE CREEK UNIT 26	X

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	Satisfactory			
WELLHEAD	Unsatisfactory	Inadequate sign.	Install sign to comply with rule 210.d.	08/30/2013

Inspector Name: BURGER, CRAIG

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Bird Protectors	1	Satisfactory			
Ancillary equipment	1	Satisfactory	Shed over wellhead.		
Vertical Heated Separator	1	Satisfactory			
Deadman # & Marked	3	Satisfactory	At least two not marked.		
Gathering Line	1	Satisfactory			

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
METHANOL	1	1000 GAL	STEEL AST	,

S/U/V: Satisfactory Comment: same berm as 400 bbl tank

Corrective Action: _____ Corrective Date: _____

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action _____ Corrective Date _____

Comment _____

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	1	400 BBLS	STEEL AST	39.332860,-107.516710	
S/U/V:	Satisfactory	Comment:			
Corrective Action:				Corrective Date:	
Paint					
Condition	Adequate				
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
Venting:					
Yes/No	Comment				
NO					
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

Predrill

Location ID: 334263

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 221342 Type: WELL API Number: 077-05135 Status: PR Insp. Status: PR

Producing Well

Comment: wellhead inside shed

Facility ID: 221987 Type: WELL API Number: 077-08589 Status: PA Insp. Status: PA

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): N
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: _____
Comment: Some thistles growing in reclaimed area where 077-08589 was located.
1003a. Debris removed? Pass CM _____ CA _____ CA Date _____
Waste Material Onsite? Pass CM _____ CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____ CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? Pass CM _____ CA _____ CA Date _____
Guy line anchors removed? _____ CM _____ CA _____ CA Date _____
Guy line anchors marked? _____ CM _____ CA _____ CA Date _____
1003b. Area no longer in use? Pass Production areas stabilized ? Pass
1003c. Compacted areas have been cross ripped? Pass
1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass
Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation _____ Pass _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Ditches	Pass			
		Gravel	Pass			
Seeding	Pass	Culverts	Pass	MHSP	Pass	

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____