



Blood Spring #1 ~ SESE S1. T9N, R54W ~ API 05-075-09233 ~ Pit ID #112220 ~ Remediation Project #7913

1 message

Eckman - DNR, Annie <annie.eckman@state.co.us>

Thu, Aug 8, 2013 at 5:06 PM

To: gfritzler12@gmail.com, gfritzler@bresnan.net

Cc: John Axelson - DNR <john.axelson@state.co.us>, "EnviroScan, OGCC" <OGCC.EnviroScan@state.co.us>

Blood Spring #1 ~ SESE S1. T9N, R54W ~ API 05-075-09233 ~ Pit ID #112220 ~ Remediation Project #7913

COGCC has reviewed the Form 27 submitted for the above referenced pit closure. The Form has been conditionally approved:

- Collect confirmation samples from each of the side walls, and at least one sample from the bottom of the pit excavation. Additionally, as directed in COGCC inspection #664001071: *Remove/remediate stained-saturated soils at separator and tank battery load out and berm.* The remediation of all of the impacted soils on site can be conducted under this project number/Form 27 along with the pit closure.
- Provide documentation of the disposal of impacted soils (manifests).

A copy of the approved Form is attached. Please refer to Remediation Project **#7913 and Pit ID #112220** when submitting subsequent data. Please contact John Axelson with any questions.

Thank you,

Annie Clements Eckman, P.G., for

John Axelson, P.G.

Environmental Protection Specialist, Northeast Region
Colorado Oil & Gas Conservation Commission

Phone: 720-929-2298

Fax: 720-929-2275

Cell: 303-877-9964

----- Forwarded message -----

From: **Gene FRITZLER** <gfritzler@bresnan.net>

Date: Tue, Jun 25, 2013 at 11:52 AM

Subject: 664001071

To: john.axelson@state.co.us

Cc: diana.burn@state.co.us

John ,

Ive enclosed Form 27 for the Bloodspring

Please contact me at 970-768-0845 or gfritzler12@gmail.com, gfritzler@bresnan.net

with any questions
Gene

 **COGCC Scan (81).pdf**
122K