

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303)894-2100 Fax:(303)894-2109



FOR OGCC USE ONLY

SPILL/RELEASE REPORT

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

Spill report taken by:

FACILITY ID:

OPERATOR INFORMATION

Name of Operator: Elm Ridge Exploration Co LLC	OGCC Operator No: 26625	Phone Numbers
Address: PO BOX 156		No: 505-632-3476 x 201
City: Bloomfield	State: NM Zip: 87413	Fax: 505-632-8151
Contact Person: Amy Mackey		E-Mail: amackey1@elmridge.net

DESCRIPTION OF SPILL OR RELEASE

Date of Incident: 11-28-12	Facility Name & No.:	County: La Plata County
Type of Facility (well, tank battery, flow line, pit): WELL		QtrQtr: SW / NE Section: 24
Well Name and Number: IGS 405		Township: 33N Range: 9W
API Number: 05-067-09073		Meridian:
Specify volume spilled and recovered (in bbls) for the following materials:		
Oil spilled: 0	Oil recov'd: 0	Water spilled: .5
Water recov'd: 0	Other spilled:	Other recov'd:
Ground Water impacted? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Surface Water impacted? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Contained within berm? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Area and vertical extent of spill: 4' x 8'	
Current land use: Agricultural	Weather conditions: Dry and Cold	
Soil/geology description: Clay top soil. Flat ground		
IF LESS THAN A MILE, report distance IN FEET to nearest.... Surface water: wetlands: buildings: 2500'		
Livestock: water wells: Depth to shallowest ground water: 300'		
Cause of spill (e.g., equipment failure, human error, etc.): Equipment failure		
Detailed description of the spill/release incident:		
Valves were at fault. New valves were installed.		

CORRECTIVE ACTION

Describe immediate response (how stopped, contained and recovered):
Changed valves and removed contaminated soil. Rebuilt tank berms to hold the volume of the tank.

Describe any emergency pits constructed:
None needed.

How was the extent of contamination determined:
Measured with soil removed.

Further remediation activities proposed (attach separate sheet if needed):
None Needed.

Describe measures taken to prevent problem from reoccurring:
Valves were faulty. They were replaced. Implemented maintaince schedule for valves.

OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact	Phone	Response

Spill/Release Tracking No: 200371705