

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

08/15/2013

Document Number:

668601235

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection
	<u>206042</u>	<u>321101</u>	<u>QUINT, CRAIG</u>	<input type="checkbox"/> 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10114 Name of Operator: S & S OIL & GAS OPERATING

Address: 107 N 4TH STE 209

City: PONCA CITY State: OK Zip: 74601

Contact Information:

Contact Name	Phone	Email	Comment
Rebol, Dave		investmentequipment@cox.net	
ONYSKIW, DENISE		denise.onyskiw@state.co.us	
LEONARD, MIKE		mike.leonard@state.co.us	

Compliance Summary:

QtrQtr: SWNE Sec: 11 Twp: 35S Range: 46W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/11/2013	668601064	SI	SI	U	P		N
08/23/2012	668200133	SI	TA	V			Y
07/27/2011	200316360	RT	SI	U			Y
06/22/2010	200257336	RT	SI	U			Y
08/03/2009	200216210	RT	SI	U			Y
02/17/2009	200207496	ES	SI	U			Y
07/16/2008	200193297	MI	SI	S			N
07/11/2007	200114839	RT	SI	S		P	N
08/01/2006	200094749	RT	AC	S		P	N
02/10/2005	200066923	RT	SI	S		P	N
08/10/2004	200058057	RT	SI	S		P	N
07/29/2003	200042220	MI	SI	S		P	N
08/08/2002	200029692	RT	AC	S		P	N
08/23/2001	200019481	RT	AC	S		P	N
02/23/2001	200015394	PR	AC	S	I	P	N
03/03/2000	200005080	RT	AC	S	I	P	N
05/04/1999	500136412	PR	AC			P	N
06/11/1998	500136411	PR	AC			P	N
02/13/1997	500136410	PR	AC			P	N

Inspector Comment:

Inspector Name: QUINT, CRAIG

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
206042	WELL	SI	01/05/2001	OW	009-06458	TSRU 701W	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	2 TRACK THROUGH PASTURE		

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	SIGN BY WELL		

Emergency Contact Number: (S/U/V) Satisfactory _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	STEEL PIPE AROUND ALL EQUIPMENT		

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 321101

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 206042 Type: WELL API Number: 009-06458 Status: SI Insp. Status: SI

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: LNSNG

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 07/16/2008

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: YES

Comment: _____

Method of Injection: PUMP FEED

Test Type: 5 Year Tbg psi: -9" HG Csg psi: 0 PSIG BH psi: _____

Insp. Status: Pass

Comment: MIRU DILLCO FLUID SERVICE, LOAD CSG W/1BBL WATER, PRESSURE CASING TO 450 PSIG, 5 MIN-445#, 10 MIN-445#, 15 MIN-445#, -5# PRES LOSS.

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Inspector Name: QUINT, CRAIG

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V:	_____	Corrective Date:	_____
Comment:	<div></div>		
CA:	<div></div>		