

Inspector Name: Baroumand, Soraya

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

08/14/2013

Document Number:

668500317

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>334426</u>	<u>334426</u>	<u>Baroumand, Soraya</u>	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 16800 Name of Operator: DELTA PETROLEUM CORP NDBA PAR PETROLEUM CORPAddress: 1301 MCKINNEY #2025City: HOUSTON State: TX Zip: 77010**Contact Information:**

Contact Name	Phone	Email	Comment
RAMOS, MARTHA		martha.ramos@state.co.us	
Barron, Seth		sbarron@conwaymackenzie.com	

Compliance Summary:QtrQtr: NWSE Sec: 29 Twp: 9S Range: 93W**Inspector Comment:**

Bond Release Inspection: The proposed location # 334426, (Known as Pad #10A) was not constructed and the 13 APDs were never drilled. Sundry filings for abandoning the APDs have been submitted. This field inspection has verified that the proposed well pad and access road were never built.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
298709	WELL	AL	10/14/2011	LO	077-09756	NVEGA 29-333	<input checked="" type="checkbox"/>
299043	WELL	AL	10/13/2011	LO	077-09758	NVEGA 29-433	<input checked="" type="checkbox"/>
299044	WELL	AL	10/13/2011	LO	077-09759	NVEGA 29-334	<input checked="" type="checkbox"/>
299045	WELL	AL	10/14/2011	LO	077-09760	NVEGA 29-332	<input checked="" type="checkbox"/>
299046	WELL	AL	10/13/2011	LO	077-09761	NVEGA 29-341	<input checked="" type="checkbox"/>
299047	WELL	AL	10/13/2011	LO	077-09762	NVEGA 29-431	<input checked="" type="checkbox"/>
299048	WELL	AL	10/13/2011	LO	077-09763	NVEGA 29-432	<input checked="" type="checkbox"/>
299049	WELL	AL	10/13/2011	LO	077-09764	NVEGA 29-231	<input checked="" type="checkbox"/>
299050	WELL	AL	10/13/2011	LO	077-09765	NVEGA 29-233	<input checked="" type="checkbox"/>
299051	WELL	AL	10/13/2011	LO	077-09766	NVEGA 29-234	<input checked="" type="checkbox"/>
299053	WELL	AL	10/14/2011	LO	077-09767	NVEGA 29-423	<input checked="" type="checkbox"/>
299054	WELL	AL	10/14/2011	LO	077-09768	NVEGA 29-424	<input checked="" type="checkbox"/>
299055	WELL	AL	10/13/2011	LO	077-09769	NVEGA 29-434	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Inspector Name: Baroumand, Soraya

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment
--------	---------

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
------	-----------------------------	---------	-------------------	---------

Predrill

Location ID: 334426

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____**Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____**Date:** _____**Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 298709 Type: WELL API Number: 077-09756 Status: AL Insp. Status: AL

Facility ID: 299043 Type: WELL API Number: 077-09758 Status: AL Insp. Status: AL

Facility ID: 299044 Type: WELL API Number: 077-09759 Status: AL Insp. Status: AL

Inspector Name: Baroumand, Soraya

Facility ID:	299045	Type:	WELL	API Number:	077-09760	Status:	AL	Insp. Status:	AL
Facility ID:	299046	Type:	WELL	API Number:	077-09761	Status:	AL	Insp. Status:	AL
Facility ID:	299047	Type:	WELL	API Number:	077-09762	Status:	AL	Insp. Status:	AL
Facility ID:	299048	Type:	WELL	API Number:	077-09763	Status:	AL	Insp. Status:	AL
Facility ID:	299049	Type:	WELL	API Number:	077-09764	Status:	AL	Insp. Status:	AL
Facility ID:	299050	Type:	WELL	API Number:	077-09765	Status:	AL	Insp. Status:	AL
Facility ID:	299051	Type:	WELL	API Number:	077-09766	Status:	AL	Insp. Status:	AL
Facility ID:	299053	Type:	WELL	API Number:	077-09767	Status:	AL	Insp. Status:	AL
Facility ID:	299054	Type:	WELL	API Number:	077-09768	Status:	AL	Insp. Status:	AL
Facility ID:	299055	Type:	WELL	API Number:	077-09769	Status:	AL	Insp. Status:	AL

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: Location is a mountain shrub-land environment.

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____ Pass _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: Proposed location was not constructed and APDs were never drilled. Sundry notices for abandoning APDs were submitted in 2011. This Report verifies that location was not built. Stake markers were found.

Inspector Name: Baroumand, Soraya

Corrective Action: _____ Date _____

Overall Final Reclamation Pass Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____

COGCC Comments

Comment	User	Date
The proposed location (COGCC Location # 334426) which is also known as Pad #10A, was not constructed and the 13 APDs were never drilled. Sundry filings for abandoning the APDs have been submitted. This field inspection has verified that the proposed well pad and access road were never built. Stake markers were found. Photos were taken during the site inspection, and appear similar to the location photos previously submitted by Delta Petroleum at the time of permit application.	baroumas	08/16/2013
Note: INSP REPORT was entered by location # 334426, with Pass Final Reclamation check-marked & location not built check-marked, and inspection status being AL check-marked for each API# (SMB).		