

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

08/20/2013

Document Number:

668601270

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection
	<u>205623</u>	<u>320972</u>	<u>QUINT, CRAIG</u>	<input type="checkbox"/> 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10383 Name of Operator: SOVEREIGN OPERATING COMPANY LLC

Address: 621 17TH STREET #950

City: DENVER State: CO Zip: 80293

Contact Information:

Contact Name	Phone	Email	Comment
Crane, Rocky	719-529-0682	rockycrane@yahoo.com	Pumper (Baca)
,	303-297-0347	sovereignenergy@aol.com	

Compliance Summary:

QtrQtr: <u>NESW</u>	Sec: <u>16</u>	Twp: <u>31S</u>	Range: <u>44W</u>				
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/18/2011	200308682	PR	PR	U			Y
09/09/2010	200272630	PR	PR	U			Y
05/05/2010	200248454	PR	PR	U			Y
04/22/2009	200209006	PR	PR	U			Y
06/13/2008	200191029	PR	PR	S			N
07/10/2007	200114807	PR	PR	U		F	Y
08/21/2002	200031365	PR	PR	S		P	N
12/13/2000	200012599	PR	PR	S	I	P	N
02/08/2000	200003991	PR	PR	S	I	P	N
03/03/1999	500135565	PR	PR			P	N
02/04/1998	500135564	PR	PR			P	N
12/26/1996	500135563	PR	PR				Y
03/09/1995	500135562	PR	PR			P	Y

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
205623	WELL	PR	08/14/1970	GW	009-06034	COPE, NELLIE 1-16	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Inspector Name: QUINT, CRAIG

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	DIRT ROAD THROUGH FARM GROUND		

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory	LEASE SIGN MOUNTED ON METER RUN		
TANK LABELS/PLACARDS	Unsatisfactory	NO TANK LABELING	Install sign to comply with rule 210.d.	11/20/2013

Emergency Contact Number: (S/U/V) _____ Satisfactory _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	WIRE PANELS AROUND WELLHEAD AND UNIT		

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gas Meter Run	3	Satisfactory			
Ancillary equipment	2	Satisfactory	ELEC PANEL, CATHOTIC RECTIFIER		
Compressor	1	Satisfactory			
Prime Mover	1	Satisfactory	ELEC MOTOR		
Vertical Separator	1	Satisfactory			
Pump Jack	1	Satisfactory	40 CHURCHILL		

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	200 BBLS	Open Top	37.342420,-102.391370
S/U/V:	Satisfactory	Comment:	200BBL OPEN TOP FIBERGLASS WATER TANK WITH ADEQUATE WILDLIFE SCREENING.	

Corrective Action:		Corrective Date:	
--------------------	--	------------------	--

Paint

Condition	
-----------	--

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Inadequate

Corrective Action	REPAIR BERM	Corrective Date	11/20/2013
-------------------	-------------	-----------------	------------

Comment	
---------	--

Facilities:	<input type="checkbox"/> New Tank	Tank ID: _____
--------------------	-----------------------------------	----------------

Contents	#	Capacity	Type	SE GPS
OTHER	1	1000 GAL	PLASTIC AST	37.342270,-102.391340

S/U/V:	Satisfactory	Comment:	1350 GALLON SLOP OIL TANK FOR COMPRESSOR DUMP.
--------	--------------	----------	--

Corrective Action:		Corrective Date:	
--------------------	--	------------------	--

Paint

Condition	
-----------	--

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 320972

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____ **Date:** _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 205623 Type: WELL API Number: 009-06034 Status: PR Insp. Status: PR

Producing Well

Comment: PRODUCING

Environmental**Spills/Releases:**

Inspector Name: QUINT, CRAIG

Type of Spill: _____	Description: _____	Estimated Spill Volume: _____
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	

Water Well:		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment:

1003a.	Debris removed?	Pass	CM	_____
	CA			CA Date _____
	Waste Material Onsite?	Pass	CM	_____
	CA			CA Date _____
	Unused or unneeded equipment onsite?	Pass	CM	_____
	CA			CA Date _____
	Pit, cellars, rat holes and other bores closed?	Pass	CM	_____
	CA			CA Date _____
	Guy line anchors removed?		CM	_____
	CA			CA Date _____
	Guy line anchors marked?		CM	_____
	CA			CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Inspector Name: QUINT, CRAIG

Top soil replaced Pass

Recontoured Pass

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment: UNUSED AREAS OF THE LOCATION ARE FARMED.

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____