

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

08/19/2013

Document Number:

668601248

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection
	<u>282016</u>	<u>337059</u>	<u>QUINT, CRAIG</u>	<input type="checkbox"/> 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100125 Name of Operator: HRC OPERATING LLCAddress: 475 17TH STREET #1500City: DENVERState: COZip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Kevin	970-354-7495 HM	Kdandrews@aol.com	785-332-6174 Cell
CARSON, SARAH	(720) 446-1015	scarson@halconresources.com	

Compliance Summary:QtrQtr: SESE Sec: 10 Twp: 5S Range: 44W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/06/2011	200316282	PR	SI	U			Y
11/09/2010	200284640	PR	SI	S			N
02/07/2008	200126443	PR	PR	S			N
11/27/2006	200099534	PR	PR	S		P	N

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
282016	WELL	PR	12/13/2005	GW	125-09759	BRENNER 10-16	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	2 TRACK THROUGH PASTURE.		

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Unsatisfactory	LEASE SIGN MOUNTED ON METER SHED HAS PREVIOUS OPERATOR.	Install sign to comply with rule 210.d.	11/19/2013

Emergency Contact Number: (S/U/V) Unsatisfactory Corrective Date: 11/19/2013

Comment: CONTACT NUMBERS ARE FOR PREVIOUS OPERATOR.

Corrective Action: INSTALL CURRENT CONTACT NUMBERS.

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
LOCATION	Satisfactory	LOCATION FENCED WITH WIRE.		

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Deadman # & Marked	4	Unsatisfactory	DEADMEN ARE NOT MARKED	MARK ALL DEADMEN	11/19/2013
Pump Jack	1	Satisfactory	25 CONVENTIONAL ON A CEMENT PAD		
Vertical Separator	1	Satisfactory	VGS IN SHED		
Ancillary equipment	1	Satisfactory	GAS SCRUBBER		
Gas Meter Run	1	Satisfactory			
Prime Mover	1	Satisfactory	KOHLER COMMAND 18 GAS ENGINE.		

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 337059

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____ **Date:** _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 282016 Type: WELL API Number: 125-09759 Status: PR Insp. Status: PR

Producing Well

Comment: PRODUCING

Environmental**Spills/Releases:**

Inspector Name: QUINT, CRAIG

Type of Spill: _____	Description: _____	Estimated Spill Volume: _____
Comment: _____		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	

Water Well:		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:			
Date Interim Reclamation Started: _____		Date Interim Reclamation Completed: _____	
Land Use: _____			
Comment: _____			
1003a.	Debris removed? <u>Pass</u>	CM _____	
	CA _____		CA Date _____
	Waste Material Onsite? <u>Pass</u>	CM _____	
	CA _____		CA Date _____
	Unused or unneeded equipment onsite? <u>Pass</u>	CM _____	
	CA _____		CA Date _____
	Pit, cellars, rat holes and other bores closed? <u>Pass</u>	CM _____	
	CA _____		CA Date _____
	Guy line anchors removed? _____	CM _____	
	CA _____		CA Date _____
	Guy line anchors marked? <u>Fail</u>	CM DEADMEN NOT MARKED	
	CA MARK ALL DEADMEN		CA Date 11/19/2013
1003b.	Area no longer in use? <u>Pass</u>		Production areas stabilized ? <u>Fail</u>
1003c.	Compacted areas have been cross ripped? _____		
1003d.	Drilling pit closed? <u>Pass</u>	Subsidence over on drill pit? <u>Pass</u>	
	Cuttings management: _____		
1003e.	Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>Pass</u>		
	Production areas have been stabilized? <u>Fail</u>	Segregated soils have been replaced? <u>Pass</u>	
RESTORATION AND REVEGETATION			
<u>Cropland</u>			

Inspector Name: QUINT, CRAIG

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass

Recontoured Pass

80% Revegetation Pass

1003 f. Weeds Noxious weeds? P

Comment: UNUSED AREAS OF THE LOCATION ARE PASTURE.

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Compaction	Pass			

S/U/V: Unsatisfactory Corrective Date: 11/19/2013

Comment: AREAS OF EROSION OFF OF WELL PAD. SEE ATTACHED PHOTOGRAPHS

CA: REPAIR AND INSTALL BMP's

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
668601249	NW LOOKING SE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3174337
668601250	WELLHEAD LOOKING EAST	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3174338
668601251	EAST SIDE OF LOCATION LOOKING WEST TO WELLHEAD	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3174339