

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

09/03/2013

Document Number:

663902115

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection
	335889	335889	LONGWORTH, MIKE	<input type="checkbox"/> 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 66571 Name of Operator: OXY USA WTP LP

Address: P O BOX 27757

City: HOUSTON State: TX Zip: 77227

Contact Information:

Contact Name	Phone	Email	Comment
Clark, Chris		Chris_Clark@oxy.com	
KELLERBY, SHAUN		shaun.kellerby@state.co.us	

Compliance Summary:

QtrQtr: <u>SWSE</u>	Sec: <u>9</u>	Twp: <u>6S</u>	Range: <u>97W</u>				
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/24/2009	200222079	CO	PR	S			N

Inspector Comment:

No evidence of AL well CC 09-58 on location

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
291105	WELL	PR	07/24/2013	GW	045-14298	CASCADE CREEK 697-9-60D	<input type="checkbox"/>
291565	WELL	PR	05/17/2012	GW	045-14445	CASCADE CREEK 697-09-52B	<input type="checkbox"/>
293833	WELL	PR	01/20/2010	GW	045-15135	CASCADE CREEK 697-09-52A	<input type="checkbox"/>
293834	WELL	PR	09/28/2012	GW	045-15136	CASCADE CREEK 697-09-44B	<input type="checkbox"/>
296404	WELL	PR	05/17/2012	GW	045-16001	CASCADE CREEK 697-09-62B	<input type="checkbox"/>
296409	WELL	PR	11/19/2009	GW	045-16006	CASCADE CREEK 697-09-60B	<input type="checkbox"/>
296410	WELL	PR	05/30/2012	GW	045-16007	CASCADE CREEK 697-09-44A	<input type="checkbox"/>
296411	WELL	PA	12/29/2010	GW	045-16008	CASCADE CREEK 697-09-46	<input type="checkbox"/>
296412	WELL	SI	09/18/2012	GW	045-16009	CASCADE CREEK 697-09-54B	<input type="checkbox"/>
296413	WELL	PR	07/01/2011	GW	045-16010	CASCADE CREEK 697-09-54A	<input type="checkbox"/>
296420	WELL	PA	12/29/2010	GW	045-16016	CASCADE CREEK 697-16-13A	<input type="checkbox"/>
296421	WELL	PR	04/23/2012	GW	045-16017	CASCADE CREEK 697-16-05	<input type="checkbox"/>
296422	WELL	PR	02/16/2012	GW	045-16018	CASCADE CREEK 697-16-04	<input type="checkbox"/>
296423	WELL	PR	04/23/2012	GW	045-16019	CASCADE CREEK 697-16-13B	<input type="checkbox"/>
296424	WELL	PR	01/16/2010	GW	045-16020	CASCADE CREEK 697-09-62A	<input type="checkbox"/>
296931	WELL	PA	12/29/2010	GW	045-16225	CASCADE CREEK 697-09-37B	<input type="checkbox"/>
296932	WELL	PR	03/01/2013	GW	045-16226	CASCADE CREEK 697-09-35C	<input type="checkbox"/>
296933	WELL	AL	12/05/2012	LO	045-16227	CASCADE CREEK 697-09-58	<input checked="" type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

296934	WELL	PR	02/22/2010	GW	045-16228	CASCADE CREEK 697-16-02A	<input type="checkbox"/>
296935	WELL	SI	08/19/2013	GW	045-16229	CASCADE CREEK 697-16-21A	<input type="checkbox"/>
296936	WELL	PR	03/01/2012	GW	045-16230	CASCADE CREEK 697-16-11A	<input type="checkbox"/>
299515	WELL	PA	12/29/2010	GW	045-17697	CASCADE CREEK 697-16-11B	<input type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 335889

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 296933 Type: WELL API Number: 045-16227 Status: AL Insp. Status: AL

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: LONGWORTH, MIKE

Comment: <input style="width: 700px;" type="text"/>			
Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
Water Well:			
		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	
Field Parameters:			
<input style="width: 300px;" type="text"/>			
Sample Location: <input style="width: 400px;" type="text"/>			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____	Wildlife Protection Devices (fired vessels): _____		

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment:

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Inspector Name: LONGWORTH, MIKE

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____