

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

08/26/2013

Document Number:

664001227

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection
	<u>219870</u>	<u>312250</u>	<u>SCHURE, KYM</u>	<input type="checkbox"/> 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290 Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVERState: COZip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
AXELSON, JOHN		john.axelson@state.co.us	
,		kgoil@msn.com	

Compliance Summary:QtrQtr: NWNE Sec: 6 Twp: 8N Range: 52W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/08/2013	667500155			V			Y
10/30/2012	667500064			V			Y
05/20/2010	200250673	ES	PR	S			Y
10/27/2009	200221063	ES	PR	U			Y
04/27/2009	200212653	ES	PR	U			Y
05/21/2008	200191202	ES	PR	U			Y
06/17/2004	200055823	ES		S		P	N
03/30/2004	200052127	ES	PR	U		F	Y
12/14/1995	500153399	PR	PR			P	N

Inspector Comment:

Compliance citations from Doc#667500155 updated as follows: Stockpiles of contaminated soils have been removed from battery area. P/W pit is currently dry, oil residue has been corrected inside berm. Non-reportable leak at compressor within shack and within containment, COGCC Inspector contacted Operator Rep. (Roy Teter 303-833-3251) informing about leak, Operator agreed to repair.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
219870	WELL	PR	01/20/1962	OW	075-07533	KNUDSEN 7	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Inspector Name: SCHURE, KYM

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 312250

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 219870 Type: WELL API Number: 075-07533 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Environmental**Spills/Releases:**

Inspector Name: SCHURE, KYM

Type of Spill: _____	Description: _____	Estimated Spill Volume: _____
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	

Water Well:		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:	
Date Interim Reclamation Started: _____	Date Interim Reclamation Completed: _____
Land Use: _____	
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
1003a.	Debris removed? _____ CM _____
	CA _____ CA Date _____
	Waste Material Onsite? _____ CM _____
	CA _____ CA Date _____
	Unused or unneeded equipment onsite? _____ CM _____
	CA _____ CA Date _____
	Pit, cellars, rat holes and other bores closed? _____ CM _____
	CA _____ CA Date _____
	Guy line anchors removed? _____ CM _____
	CA _____ CA Date _____
	Guy line anchors marked? _____ CM _____
	CA _____ CA Date _____
1003b.	Area no longer in use? _____ Production areas stabilized ? _____
1003c.	Compacted areas have been cross ripped? _____
1003d.	Drilling pit closed? _____ Subsidence over on drill pit? _____
	Cuttings management: _____
1003e.	Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
	Production areas have been stabilized? _____ Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION	
<u>Cropland</u>	

Inspector Name: SCHURE, KYM

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: No surface erosion from stormwater runoff observed

CA: _____