

Field Sampling Data Sheet

COGCC Facility ID: _____

Site Address: 1282 County Road 125 Bennett CO 80102

Site Contact: Eldon Auxier / Sherry Zunther

Phone #: 303-921-6717 / 303-622-9227

Date of Sample: 3/27/13

Sample Type (baseline, post-drill, complaint): baseline

Oil & Gas Well API Number: 05-005-07204

Property Owner Name: Eldon Auxier

Property Owner Phone Number: 303 921 6717

Property Owner Mailing Address: 26 Silver Point Dr.

Elmore, AI 36025-1009

Individuals Present (Who was on-site during the sampling event?)

P Young, A Smethers

Water Well Information from Permit Records

Permit No.: 252883

Receipt No.: 0514831

Total Depth (ft.): 560

Static Water Level (ft.): 180

Yield (GPM): 10

Well Diameter (in.): 6 5/8 steel

Water Well Information Onsite

GPS Location (field): 39.73402660° N; 104.47015402° W

GPS Location (post-processed): _____

Water well casing height (in.): ~24

Ground Elevation (ft.): TBD How determined: _____

Approximate distance to the Oil & Gas well pad: 972'

%LEL at wellhead (if measured): NA

%CH₄ at wellhead (if measured): NA

Weather conditions: clear/sunny, ~45° F

Photo(s) Taken?

Handed Out Landowner Introduction Letter? **N**

Handed Out FAQ Sheet? **N**

Handed Out "How Well Do You Know Your Water Well" Pamphlet? **N**

Where was the Sample Taken? outside tap

(Outside Tap, Well House, Kitchen Tap, Spring, Seep, etc.)

Condition of the Well, Spring or Seep (Wellhead sealed? Does the ground slope away from the well?, Visible contamination of spring/seep?, etc.):

wellhead sealed, ground gently slopes to east.
no visible contamination.

Field Sampling Data Sheet – Page 2

Landowner Comments on Water Quality: None

Water Quality Field Parameters:

Time	Purge Vol. (gal)	pH	Conductivity	Temp	Color/Appearance /Sediment	Odor	Bubbles/Effervescence?
1302	10	8.4	.739	14.24	colorless, clear	None	no effervescence, few bubbles in line
1305	13	8.4	.739	14.08	SAA	SAA	SAA
1308	16	8.4	.732	13.80	SAA	SAA	SAA

Purge rate (gpm): ~1 Purge Time (min.): 16

Total Purge Volume (gal.): ~16

Sampling flow rate (gpm): ~.25

ADDITIONAL INFORMATION:

Bubbles in sampling line prevented sampling NGI w/ no headspace. Small dog present unrestricted on property - not aggressive. Well located behind house ~40' from SE corner.

Sampler's Name Daisy Young Company: CB? I

Sampler's Signature (Print) Daisy Young Date: 3/27/13