

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:  
09/20/2013

Document Number:  
668601457

Overall Inspection:  
Satisfactory

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	<u>208470</u>	<u>321907</u>	<u>QUINT, CRAIG</u>	2A Doc Num:	

**Operator Information:**

OGCC Operator Number: 17180 Name of Operator: CITATION OIL & GAS CORP  
 Address: 14077 CUTTEN RD  
 City: HOUSTON State: TX Zip: 77269

**Contact Information:**

Contact Name	Phone	Email	Comment
Rogers, Bob	719-767-8851	brogers@cogc.com	719-340-1445 cell
ONYSKIW, DENISE		denise.onyskiw@state.co.us	
ELSOM, LEE ANN	281-891-1577 EXT 1577	lelsom@cogc.com	
Smith, Martha		MSmith@cogc.com	
LEONARD, MIKE		mike.leonard@state.co.us	

**Compliance Summary:**

QtrQtr: SESE Sec: 13 Twp: 12S Range: 51W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/16/2013	668600793	IJ	AC	S			N
06/07/2011	200312255	RT	AC	S			N
03/04/2010	200234776	RT	AC	S			N
04/28/2009	200209374	MI	AC	S			N
05/23/2008	200190249	RT	AC	S			N
03/15/2007	200106540	RT	AC	S		P	N
07/21/2006	200094711	RT	AC	S		P	N
06/23/2005	200074075	RT	AC	S		P	N
12/20/2004	200064215	MI	SI	S		P	N
07/22/2004	200058149	RT	AC	S		P	N
08/15/2003	200043164	RT	AC	S		P	N
07/30/2002	200029491	RT	AC	S		P	N
12/05/2000	200012713	PR	AC	S	I	P	N
09/01/2000	200010811	MI	AC	S	I	P	N
08/17/2000	200010815	MI	AC	S	I	P	N
12/22/1997	500140614	PR	AC			P	N
08/23/1996	500140612	PR	AC			P	N
07/21/1995	500140613	PR	SI			P	N

Inspector Name: QUINT, CRAIG

08/16/1994	500140611		PR			F	Y
06/14/1994	500140610		PR			P	N
02/16/1994	500140609		WO			P	

**Inspector Comment:**

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
150377	UIC ENHANCED RECOVERY	AC	01/17/1995		-	SPEAKER UNIT	<input checked="" type="checkbox"/>
208470	WELL	IJ	08/30/1995	OW	017-07405	SPEAKER 44-13 8	<input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	PARTIALLY ELEVATED GRAVEL ROAD THROUGH PASTURE WITH A CATTLE GUARD AT LOCATION ENTRANCE.		

**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	LEASE SIGN BY METER RUN BY WELL.		

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

**Venting:**

Yes/No	Comment

<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 321907

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_

Other BMPs: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 150377 Type: UIC API Number: - Status: AC Insp. Status: WK

**Underground Injection Control**

UIC Violation: \_\_\_\_\_

Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
(e.g. 30 psig or -30" Hg) Inj Zone: \_\_\_\_\_

TC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: \_\_\_\_\_

Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTRReq: NO

Comment: \_\_\_\_\_

Method of Injection: PUMP FEED

Test Type: Verification of Repairs Tbg psi: 0 PSIG Csg psi: 0 PSIG BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: MIRU EXTREME HEAT, LOAD ANNULUS W/ 40 BBLS WATER, PRESSURE CSG TO 735 PSIG, 5 MIN-725#, 10 MIN-720#, 15 MIN-720#, -15# PRESSURE LOSS (PASS).

**Workover**

Comment: EASTERN COLORADO WELL SERVICE RIG # TRIP TUBING AND PACKER. CLEAN OUT RAT HOLE AND REPERF ZONE.

Facility ID: 208470 Type: WELL API Number: 017-07405 Status: IJ Insp. Status: WK

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation

Multi-Well Location

<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
		Culverts	Pass			
		Ditches	Pass			

S/U/V: Satisfactory                      Corrective Date: \_\_\_\_\_

Comment:

CA: