

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

09/12/2013

Document Number:

663401186

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	
	216323	326370	LABOWSKIE, STEVE	2A Doc Num:	

Operator Information:

OGCC Operator Number: 100264 Name of Operator: XTO ENERGY INC

Address: 382 CR 3100

City: AZTEC State: NM Zip: 87410

Contact Information:

Contact Name	Phone	Email	Comment
Percell, Bob	(970) 247-7708/ (719) 342-1150	bob_percell@xtoenergy.com	Durango District Operations
Harrison, Lyndon		lyndon_harrison@xtoenergy.com	Durango, Raton
Kardos, Kelly		kelly_kardos@xtoenergy.com	Piceance
Hixon, Logan		logan_hixon@xtoenergy.com	

Compliance Summary:

QtrQtr: NWNE Sec: 6 Twp: 34N Range: 8W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/12/2010	200267396	PR	PR	S			N
06/20/2006	200099665	PR	PR	S		P	N
06/28/2004	200058346	PR	PR	S		P	Y
09/11/2002	200032142	PR	PR	S		P	N
12/12/2001	200023305	PR	PR	S		P	N
11/08/2000	200012112	PR	PR	S		P	N
09/14/1999	500150510	PR	PR			P	N
11/10/1997	500150509	PR	PR			P	N
10/18/1996	500150508	PR	PR			P	N
10/16/1995	500150507	PR	PR				N

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
216323	WELL	PR	05/20/1993	GW	067-07929	SHIELDS 2-6	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Inspector Name: LABOWSKIE, STEVE

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	Note: access road has tall vegetation in and willows encroaching in several places.		

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gas Meter Run	1				
Ancillary equipment	1				
Bird Protectors	1				
Deadman # & Marked	4				
Flow Line	1				
Vertical Heated Separator	1				

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 326370

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____ **Date:** _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 216323 Type: WELL API Number: 067-07929 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental**Spills/Releases:**

Inspector Name: LABOWSKIE, STEVE

Type of Spill: _____	Description: _____	Estimated Spill Volume: _____
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	

Water Well:		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment:

1003a.	Debris removed?	Pass	CM	_____	CA	_____	CA Date	_____
	Waste Material Onsite?	Pass	CM	_____	CA	_____	CA Date	_____
	Unused or unneeded equipment onsite?	Pass	CM	_____	CA	_____	CA Date	_____
	Pit, cellars, rat holes and other bores closed?	Pass	CM	_____	CA	_____	CA Date	_____
	Guy line anchors removed?		CM	_____	CA	_____	CA Date	_____
	Guy line anchors marked?	Pass	CM	_____	CA	_____	CA Date	_____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Inspector Name: LABOWSKIE, STEVE

Top soil replaced Pass

Recontoured Pass

Perennial forage re-established Pass

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			
Compaction	Pass					

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____