

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

10/04/2013

Document Number:

663902263

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection <input type="checkbox"/>
	334826	334826	LONGWORTH, MIKE	2A Doc Num: _____

**Operator Information:**

OGCC Operator Number:

Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: 1001 17TH STREET - SUITE #1200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Moss, Brad	(970) 285-9377	Brad.Moss@WPXEnergy.com	Production foreman
KELLERBY, SHAUN		shaun.kellerby@state.co.us	
Gardner, Michael	970/285-9377 ext. 2760	Michael.Gardner@WPXEnergy.com	Principal Environmental Specialist

**Compliance Summary:**QtrQtr: SESW Sec: 31 Twp: 6S Range: 95W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
211075	WELL	PR	09/07/2001	GW	045-06833	DOE 1-M-31	<input checked="" type="checkbox"/>
260367	WELL	PR	05/07/2002	GW	045-07849	FEDERAL PA 23-31	<input checked="" type="checkbox"/>
260368	WELL	PR	06/05/2002	GW	045-07850	FEDERAL PA 13-31	<input checked="" type="checkbox"/>
292999	WELL	PR	10/31/2008	GW	045-14832	FEDERAL PA 524-31	<input checked="" type="checkbox"/>
293000	WELL	SI	02/14/2013	GW	045-14833	FEDERAL PA 24-31	<input checked="" type="checkbox"/>
293002	WELL	PR	10/30/2008	GW	045-14834	FEDERAL PA 423-31	<input checked="" type="checkbox"/>
293019	WELL	PR	10/31/2008	GW	045-14835	FEDERAL PA 314-31	<input checked="" type="checkbox"/>
293020	WELL	PR	10/31/2008	GW	045-14836	FEDERAL PA 413-31	<input checked="" type="checkbox"/>
293021	WELL	PR	10/31/2008	GW	045-14837	FEDERAL PA 313-31	<input checked="" type="checkbox"/>
293022	WELL	PR	10/31/2008	GW	045-14838	FEDERAL PA 534-31	<input checked="" type="checkbox"/>
293030	WELL	PR	10/27/2008	GW	045-14839	FEDERAL PA 522-31	<input checked="" type="checkbox"/>
293032	WELL	PR	10/31/2008	GW	045-14831	FEDERAL PA 434-31	<input checked="" type="checkbox"/>
293037	WELL	PR	10/31/2008	GW	045-14830	FEDERAL PA 414-31	<input checked="" type="checkbox"/>
293110	WELL	PR	10/27/2008	GW	045-14891	FEDERAL PA 323-31	<input checked="" type="checkbox"/>

**Equipment:****Location Inventory**

Inspector Name: LONGWORTH, MIKE

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

### Location

#### Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	Over night rain/snow storms. Road is wet and slippery. Continuee maintaining road		

#### Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			
CONTAINERS	Satisfactory			
WELLHEAD	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

#### Good Housekeeping:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
STORAGE OF SUPL	Satisfactory	Tubing trailer on location. Move trailer from location if or when it is not in use.		

#### Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

#### Fencing/:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
SEPARATOR	Satisfactory			
TANK BATTERY	Satisfactory			

#### Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Bird Protectors	8	Satisfactory			
Horizontal Heated Separator	14	Satisfactory			

Inspector Name: LONGWORTH, MIKE

Ancillary equipment	3	Satisfactory	Well treatment chemical totes		
Plunger Lift	14	Satisfactory			

**Facilities:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST	39.476300,108.044110

S/U/V:	Satisfactory	Comment:	
Corrective Action:		Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

**Facilities:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST	,

S/U/V:	Satisfactory	Comment:	
Corrective Action:		Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

<b>Venting:</b>	
Yes/No	Comment

<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 334826

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/U/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

S/U/V: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_

Other BMPs: \_\_\_\_\_

**Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 211075 Type: WELL API Number: 045-06833 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID:	260367	Type:	WELL	API Number:	045-07849	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	260368	Type:	WELL	API Number:	045-07850	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	292999	Type:	WELL	API Number:	045-14832	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	293000	Type:	WELL	API Number:	045-14833	Status:	SI	Insp. Status:	SI
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	293002	Type:	WELL	API Number:	045-14834	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	293019	Type:	WELL	API Number:	045-14835	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	293020	Type:	WELL	API Number:	045-14836	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	293021	Type:	WELL	API Number:	045-14837	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	293022	Type:	WELL	API Number:	045-14838	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	293030	Type:	WELL	API Number:	045-14839	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	293032	Type:	WELL	API Number:	045-14831	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	293037	Type:	WELL	API Number:	045-14830	Status:	PR	Insp. Status:	PR

**Producing Well**Comment: **Producing well**

Facility ID: 293110 Type: WELL API Number: 045-14891 Status: PR Insp. Status: PR

**Producing Well**Comment: **Producing well****Environmental****Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

**Water Well:**

Lat Long

DWR Receipt Num: Owner Name: GPS :

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? Pass CM

CA CA Date

Waste Material Onsite? Pass CM

CA CA Date

Unused or unneeded equipment onsite? Pass CM

CA CA Date

Pit, cellars, rat holes and other bores closed? Pass CM

CA CA Date

Guy line anchors removed? In CM

CA CA Date

Guy line anchors marked? CM

CA CA Date

Inspector Name: LONGWORTH, MIKE

- 1003b. Area no longer in use? In Production areas stabilized ? Pass
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

#### RESTORATION AND REVEGETATION

##### Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

##### Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: Continue seeding and revegetation of hillsides and unused areas of location. Submit form 4 for Interim reclamation

Overall Interim Reclamation Fail

#### **Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

#### **Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gradient Terraces	Pass			
Compaction	Pass	Berms	Pass	MHSP	Pass	
Gravel	Pass	Culverts	Pass			
Ditches	Pass	Compaction	Pass			
Seeding	Fail	Ditches	Fail			

Inspector Name: LONGWORTH, MIKE

S/U/V: Satisfactory Corrective Date: \_\_\_\_\_

Comment: Continue revegetation efforts and clean out ditches and culverts

CA: \_\_\_\_\_

Pits: ☐ NO SURFACE INDICATION OF PIT