

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



|    |    |    |    |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:  
10/03/2013

Document Number:  
670200926

Overall Inspection:  
Satisfactory

**FIELD INSPECTION FORM**

|                     |               |               |                      |                          |             |
|---------------------|---------------|---------------|----------------------|--------------------------|-------------|
| Location Identifier | Facility ID   | Loc ID        | Inspector Name:      | On-Site Inspection       | 2A Doc Num: |
|                     | <u>278181</u> | <u>336038</u> | <u>BURGER, CRAIG</u> | <input type="checkbox"/> |             |

**Operator Information:**

OGCC Operator Number: \_\_\_\_\_

Name of Operator: URSA OPERATING COMPANY LLC

Address: 602 SAWYER STREET #710

City: HOUSTON State: TX Zip: 77007

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name    | Phone | Email                      | Comment                            |
|-----------------|-------|----------------------------|------------------------------------|
| Bleil, Robert   |       | rbleil@ursaresources.com   | Regulatory & Environmental Manager |
| Kellerby, Shaun |       | Shaun.Kellerby@state.co.us | NW Field Supervisor                |
| Smith, Cody     |       | csmith@ursaresources.com   |                                    |

**Compliance Summary:**

QtrQtr: SENW Sec: 8 Twp: 6S Range: 92W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 12/10/2010 | 200287119 | PR         | SI          | S                            |          |                | N               |

**Inspector Comment:**

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   |   |
|-------------|------|--------|-------------|------------|-----------|-----------------|---|
| 278178      | WELL | PR     | 03/30/2012  | GW         | 045-10848 | RIVER RANCH B1  | X |
| 278181      | WELL | PR     | 06/11/2013  | GW         | 045-10851 | RIVER RANCH B2  | X |
| 299122      | WELL | XX     | 06/01/2012  | LO         | 045-17564 | River Ranch B3  |   |
| 299123      | WELL | XX     | 06/01/2012  | LO         | 045-17565 | River Ranch B10 |   |
| 299124      | WELL | XX     | 06/01/2012  | LO         | 045-17566 | River Ranch B4  |   |
| 299125      | WELL | XX     | 06/01/2012  | LO         | 045-17567 | River Ranch B7  |   |
| 299126      | WELL | XX     | 06/01/2012  | LO         | 045-17568 | River Ranch B8  |   |
| 299127      | WELL | XX     | 06/01/2012  | LO         | 045-17569 | River Ranch B9  |   |
| 299128      | WELL | XX     | 06/01/2012  | LO         | 045-17570 | River Ranch B11 |   |

**Equipment:**

Location Inventory

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

Emergency Contact Number: (S/U/V) \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

| <b>Spills:</b>                                         |      |        |                   |         |
|--------------------------------------------------------|------|--------|-------------------|---------|
| Type                                                   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

| <b>Venting:</b> |         |
|-----------------|---------|
| Yes/No          | Comment |
|                 |         |

| <b>Flaring:</b> |                             |         |                   |         |
|-----------------|-----------------------------|---------|-------------------|---------|
| Type            | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|                 |                             |         |                   |         |

**Predrill**

Location ID: 336038

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/U/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

|              |         |            |         |
|--------------|---------|------------|---------|
| Erosion BMPs | Present | Other BMPs | Present |
|              |         |            |         |

S/U/V: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_

Other BMPs: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 278178 Type: WELL API Number: 045-10848 Status: PR Insp. Status: PR

**BradenHead**

Comment: Annual bradenhead tset.  
Initial pressures: tube:632, casing:1117, braden:220 psi.  
Final pressures: tube:632, casing:1118, braden: 12 psi.  
Did not produce liquid. Did not completely blow down.  
Braden is piped underground to combustor.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

Facility ID: 278181 Type: WELL API Number: 045-10851 Status: PR Insp. Status: PR

**BradenHead**

Comment: Annual bradenhead tset.  
Initial pressures: tube:351, casing:971, braden:296 psi.  
Final pressures: tube: 372, casing:977, braden:30 psi.  
Produced about 1 gallon of mud/liquid at low pressure. Did not completely blow down.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

| <b>Storm Water:</b> |                 |                         |                       |               |                          |         |
|---------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs    | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|                     |                 |                         |                       |               |                          |         |

S/U/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT