

Inspector Name: BROWNING, CHUCK

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:

10/01/2013

Document Number:

668401737

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|---------------|---------------|------------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>286510</u> | <u>316575</u> | <u>BROWNING, CHUCK</u> | <input type="checkbox"/> | |

Operator Information:

OGCC Operator Number:

Name of Operator: GENESIS GAS & OIL COLORADO LLCAddress: 1701 WALNUT STREET - 4TH FLCity: KANSAS CITY State: MO Zip: 64108☐ THIS IS A FOLLOW UP INSPECTION☐ FOLLOW UP INSPECTION REQUIRED☒ NO FOLLOW UP INSPECTION REQUIRED☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|----------------------------|-----------------|
| Jensen, David | (816) 222-7500 | djensen@genesisco.com | Exec. VP |
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |

Compliance Summary:QtrQtr: SESE Sec: 33 Twp: 2N Range: 100W**Inspector Comment:**

Wellhead w/ pump jack. Vertical Separator/Telemetry in housing. Gathering line. Well shut in 1/2013. Mit due by 12/2014. No Emergency contact information.

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|-------------------------------------|
| 286510 | WELL | SI | 05/14/2013 | GW | 103-10889 | FLETCHER GULCH 33-44 | SI | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Signs/Marker: | | | | |
|---------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| BATTERY | Satisfactory | | | |

Emergency Contact Number: (S/U/V) UnsatisfactoryCorrective Date: 01/09/2014Comment: No emergency contact informationCorrective Action: Install signs to comply with rule 210.b.(2).

Inspector Name: BROWNING, CHUCK

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Equipment: | | | | | |
|--------------------|---|-----------------------------|---------|-------------------|---------|
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Pump Jack | 1 | Satisfactory | | | |
| Deadman # & Marked | 4 | Satisfactory | | | |
| Vertical Separator | 1 | Satisfactory | | | |
| Gas Meter Run | 1 | Satisfactory | | | |

| Venting: | | |
|-----------------|---------|--|
| Yes/No | Comment | |
| NO | | |

| Flaring: | | | | |
|-----------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 286510

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 286510 Type: WELL API Number: 103-10889 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

S/V: _____ CA Date: _____

CA: _____

Comment: Wellhead w/ pump jack. Vertical Separator/Telemetry in housing. Gathering line.
Well shut in 1/2013. Mit due by 12/2014.
No Emergency contact information.

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? Pass CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Inspector Name: BROWNING, CHUCK

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT