

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



|    |    |    |    |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

10/21/2013

Document Number:

600000017

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

|                     |             |        |                  |  |
|---------------------|-------------|--------|------------------|--|
| Location Identifier | Facility ID | Loc ID | Inspector Name:  | On-Site Inspection                         |
|                     | 256440      | 330917 | JOHNSON, RANDELL | <input type="checkbox"/> 2A Doc Num: _____ |

**Operator Information:**

OGCC Operator Number:

Name of Operator: KERR-MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-☐ THIS IS A FOLLOW UP INSPECTION☐ FOLLOW UP INSPECTION REQUIRED☒ NO FOLLOW UP INSPECTION REQUIRED☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED**Contact Information:**

| Contact Name      | Phone                             | Email                        | Comment                    |
|-------------------|-----------------------------------|------------------------------|----------------------------|
| Avant, Paul       | O:720-929-6457,<br>C:720-273-2688 | paul.avant@anadarko.com      | Rockies Regulatory Affairs |
| Kilcrease, Keith  | 970-506-5926                      | keith.kilcrease@anadarko.com | Production Superintendent  |
| ELLSWORTH, STUART |                                   | stuart.ellsworth@state.co.us |                            |

**Compliance Summary:**QtrQtr: SWNW Sec: 8 Twp: 2N Range: 67W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 06/02/2005 | 200071795 | PR         | PR          | S                            |          | P              | N               |
| 10/20/2004 | 200062056 | PR         | PR          | S                            |          | P              | N               |

**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status                            |
|-------------|------|--------|-------------|------------|-----------|---------------|--|
| 256440      | WELL | PR     | 09/23/2011  | OW         | 123-19870 | VOGL 5-8A     | FR <input checked="" type="checkbox"/> |

**Equipment:****Location Inventory**

|                             |                        |                     |                         |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____     | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____  | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____      | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____      | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

|                      |                             |         |                   |         |
|----------------------|-----------------------------|---------|-------------------|---------|
| <b>Signs/Marker:</b> |                             |         |                   |         |
| Type                 | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD             | Satisfactory                |         |                   |         |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

|                |          |           |   |            |
|----------------|----------|-----------|---|------------|
| <b>Spills:</b> |          |           |   |            |
| Type           | Area     | Volume    | Corrective action   | CA Date    |
| Crude Oil      | WELLHEAD | <= 5 bbls | Repair leak at wellhead/Remove or remediate oil-contaminated soil at wellhead | 11/21/2013 |

☐ Multiple Spills and Releases?

|                 |                             |              |                   |         |
|-----------------|-----------------------------|--------------|-------------------|---------|
| <b>Fencing:</b> |                             |              |                   |         |
| Type            | Satisfactory/Unsatisfactory | Comment      | Corrective Action | CA Date |
| WELLHEAD        | Satisfactory                | Pipe fencing |                   |         |

|                   |   |                             |  |         |
|-------------------|---|-----------------------------|--|---------|
| <b>Equipment:</b> |   |                             |  |         |
| Type              | # | Satisfactory/Unsatisfactory | Comment  | CA Date |
| Plunger Lift      | 1 | Satisfactory                | SE corner of fence around wellhead<br>40.15429, -<br>104.92105 |         |

|   |              |          |   |                       |
|---|--------------|----------|---|-----------------------|
| <b>Facilities:</b> <input type="checkbox"/> New Tank Tank ID: _____ |              |          |   |                       |
| Contents  | #            | Capacity | Type  | SE GPS                |
|   |              |          | CENTRALIZED BATTERY   | 40.157730,-104.914340 |
| S/U/V:  | Satisfactory | Comment: | Centralized battery services Cheng 3-8A (123-20611), Alfred D. Sater Unit 2 (123-15315), Prominence 4-8 (123-23013) and Vogl 5-8A (123-19870)/See related inspection document #600000015 for further information concerning shared facilities and equipment |                       |

|                    |  |                  |  |
|--------------------|--|------------------|--|
| Corrective Action: |  | Corrective Date: |  |
|--------------------|--|------------------|--|

|                  |          |  |  |  |
|------------------|----------|--|--|--|
| <b>Paint</b>     |          |  |  |  |
| Condition        | Adequate |  |  |  |
| Other (Content)  | _____    |  |  |  |
| Other (Capacity) | _____    |  |  |  |
| Other (Type)     | _____    |  |  |  |

|                   |          |                     |                     |                 |
|-------------------|----------|---------------------|---------------------|-----------------|
| <b>Berms</b>      |          |                     |                     |                 |
| Type              | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance     |
| Metal             | Adequate | Walls Sufficient    | Base Sufficient     | Adequate        |
| Corrective Action |          |                     |                     | Corrective Date |
| Comment           |          |                     |                     |                 |

|                 |         |  |
|-----------------|---------|--|
| <b>Venting:</b> |         |  |
| Yes/No          | Comment |  |
| NO              |         |  |

|                 |                             |         |                   |         |
|-----------------|-----------------------------|---------|-------------------|---------|
| <b>Flaring:</b> |                             |         |                   |         |
| Type            | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|                 |                             |         |                   |         |

**Predrill**

Location ID: 256440

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/U/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 256440 Type: WELL API Number: 123-19870 Status: PR Insp. Status: FR

**Producing Well**

Comment: PR

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Inspector Name: JOHNSON, RANDELL

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

**Cropland**

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Inspector Name: JOHNSON, RANDELL

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_ P \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_ Pass \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment    |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|------------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |            |
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |            |
| Other            | Pass            | Other                   | Pass                  |               |                          | Vegetation |

S/U/V: Satisfactory \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT