


| | | | | | | |
|--|---|--|----|----|----|----|
| FORM INSP <small>Rev 05/11</small> | State of Colorado Oil and Gas Conservation Commission <small>1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109</small> |  | DE | ET | OE | ES |
|--|---|--|----|----|----|----|

FIELD INSPECTION FORM

| | | | | | |
|---------------------|-------------|--------|-----------------|---|-------------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ |
| | 290565 | 336155 | QUINT, CRAIG | | |

Inspection Date:
10/25/2013

Document Number:
668601589

Overall Inspection:
Satisfactory

Operator Information:

OGCC Operator Number: _____

Name of Operator: KERR-MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|------------------------------|---------------------------|
| Kilcrease, Keith | | keith.kilcrease@anadarko.com | Production Superintendent |

Compliance Summary:

QtrQtr: SWSW Sec: 35 Twp: 3N Range: 68W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 09/20/2012 | 668700259 | PR | PR | S | P | | N |
| 02/23/2011 | 200300191 | SR | PR | U | F | | N |
| 07/10/2009 | 200228919 | PR | PR | S | | | N |

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|---|
| 240153 | WELL | PR | 09/14/2006 | OW | 123-07941 | CARL H ADLER 1 | FR | X |
| 289783 | WELL | PR | 11/11/2008 | OW | 123-24914 | CARMA 14-35 | FR | X |
| 290565 | WELL | PR | 11/14/2008 | OW | 123-25141 | CARMA 34-35 | FR | X |
| 290676 | WELL | PR | 11/21/2008 | OW | 123-25189 | CARMA 23-35 | FR | X |
| 291195 | WELL | PA | 10/03/2008 | OW | 123-25988 | CARMA 35-35 | FR | X |

Equipment: Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Lease Road: | | | | |
|--------------------|-----------------------------|----------------------------|-------------------|------|
| Type | Satisfactory/Unsatisfactory | comment | Corrective Action | Date |
| Access | Satisfactory | DIRT ROAD THROUGH PASTURE. | | |

| Signs/Marker: | | | | |
|----------------------|-----------------------------|----------------------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD | Satisfactory | LEASE SIGNS BY WELLS | | |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Fencing/: | | | | |
|------------------|-----------------------------|--|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD | Satisfactory | CHAIN LINK FENCING AROUND WELLHEAD ON CARMA 34-35, CARL H ADLER 1. | | |

| Equipment: | | | | | |
|-------------------|---|-----------------------------|-----------------------------|-------------------|---------|
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Plunger Lift | 1 | Satisfactory | PLUNGER LIFT ON CARMA 34-35 | | |

| Facilities: | | | | | |
|-----------------------------------|---|------------------------------------|---------------------|-----------------------|--|
| <input type="checkbox"/> New Tank | | Tank ID: _____ | | | |
| Contents | # | Capacity | Type | SE GPS | |
| | | | CENTRALIZED BATTERY | 40.180900,-104.978290 | |
| S/U/V: | | Comment: CENTRAL BATTERY 1350' NNW | | | |
| Corrective Action: | | | | Corrective Date: | |

Paint

Condition: _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

| Berms | | | | | |
|-------------------|----------|---------------------|---------------------|-----------------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |

| | |
|-----------------|---------|
| Venting: | |
| Yes/No | Comment |
| | |

| | | | | |
|-----------------|-----------------------------|---------|-------------------|---------|
| Flaring: | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 290565

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/UV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/UV: _____ **Comment:**

CA: **Date:** _____

Wildlife BMPs:

S/UV: _____ **Comment:**

CA: **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 240153 Type: WELL API Number: 123-07941 Status: PR Insp. Status: FR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/V: _____ CA Date: _____
CA: _____

Comment: WELL SHUT IN AND FLOWLINES ARE DISCONNECTED, FRAC TANKS ON LOCATION, PREPARING TO RE-FRAC WELLS.

Facility ID: 289783 Type: WELL API Number: 123-24914 Status: PR Insp. Status: FR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/V: _____ CA Date: _____
CA: _____

Comment: WELL SHUT IN AND FLOWLINES ARE DISCONNECTED, FRAC TANKS ON LOCATION, PREPARING TO RE-FRAC WELLS.

Facility ID: 290565 Type: WELL API Number: 123-25141 Status: PR Insp. Status: FR

Producing Well

Comment: PRODUCING

Facility ID: 290676 Type: WELL API Number: 123-25189 Status: PR Insp. Status: FR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/V: _____ CA Date: _____
CA: _____

Comment: WELL SHUT IN AND FLOWLINES ARE DISCONNECTED, FRAC TANKS ON LOCATION, PREPARING TO RE-FRAC WELLS.

Facility ID: 291195 Type: WELL API Number: 123-25988 Status: PA Insp. Status: FR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/V: _____ CA Date: _____
CA: _____

Comment: WELLHEAD HAS NOT BEEN CUT, CAPPED AND BURIED. CUT, CAP AND COVER WELLHEAD.

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____
 Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____
 Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____

Comment: _____
 Corrective Action: _____ Date _____
 Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

| Storm Water: | | | | | | |
|---------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| | | | | | | |

S/U/V: _____ Corrective Date: _____
 Comment: _____
 CA: _____

Pits: NO SURFACE INDICATION OF PIT