

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:
10/31/2013Document Number:
600000111Overall Inspection:
Satisfactory**FIELD INSPECTION FORM**

| | | | | |
|---------------------|-------------|--------|------------------|--|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection |
| | 250325 | 329974 | JOHNSON, RANDELL | <input type="checkbox"/> 2A Doc Num: _____ |

Operator Information:

OGCC Operator Number: _____

Name of Operator: KERR-MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-----------------------------------|------------------------------|----------------------------|
| Kilcrease, Keith | 970-506-5926 | keith.kilcrease@anadarko.com | Production Superintendent |
| Avant, Paul | O:720-929-6457, C:720-273-2688 | paul.avant@anadarko.com | Rockies Regulatory Affairs |

Compliance Summary:QtrQtr: SWNE Sec: 11 Twp: 3N Range: 67W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 06/28/2012 | 667600491 | PR | PR | S | | | N |
| 10/16/2006 | 200098553 | PR | PR | S | | P | N |
| 07/14/1994 | 500176871 | | PR | | | P | N |
| 04/13/1994 | 500176870 | | WO | | | F | N |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|--|
| 250325 | WELL | PR | 06/12/1994 | GW | 123-18128 | PSC 32-11 | FR <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Signs/Marker: | | | | |
|----------------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| BATTERY | Satisfactory | | | |
| WELLHEAD | Satisfactory | | | |
| TANK LABELS/PLACARDS | Satisfactory | | | |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Fencing/: | | | | |
|--------------------|-----------------------------|---------------------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD | Satisfactory | Pipe fencing | | |
| IGNITOR/COMBUST OR | Satisfactory | Barbed wire fencing | | |
| TANK BATTERY | Satisfactory | Barbed wire fencing | | |
| SEPARATOR | Satisfactory | Barbed wire fencing | | |

| Equipment: | | | | | |
|-----------------------------|---|-----------------------------|---|-------------------|---------|
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Gas Meter Run | 3 | Satisfactory | Check meters on outlets of separators/SE corner of fence around meter runs and separators 40.24052, - 104.85621 | | |
| Emission Control Device | 1 | Satisfactory | SE corner of fence around ECD 40.24009, - 104.85652 | | |
| Horizontal Heated Separator | 3 | Satisfactory | SE corner of fence around meter runs and separators 40.24052, - 104.85621 | | |
| Plunger Lift | 1 | Satisfactory | SE corner of fence around wellhead 40.24164, - 104.85641 | | |
| Gas Meter Run | 3 | Satisfactory | Pipeline meters/SE corner of fence around meter runs and separators 40.24052, - 104.85621 | | |

| | | | | |
|--------------------|--------------|-----------------------------------|--|-----------------------|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS |
| | | | CENTRALIZED BATTERY | 40.240260,-104.856220 |
| S/U/V: | Satisfactory | Comment: | Centralized battery services PSC 32-11 (123-18128), PSC 23-11 (123-18007), PSC 22-11 (123-18006) & PSC 21-11 (123-18005) | |
| Corrective Action: | | | | Corrective Date: |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| | | | | |
|-------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| | | | |
|-------------------|--|-----------------|--|
| Corrective Action | | Corrective Date | |
| Comment | | | |

| | | | | |
|--------------------|--------------|-----------------------------------|----------------|-----------------------|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS |
| CRUDE OIL | 2 | 400 BBLS | STEEL AST | 40.240260,-104.856220 |
| S/U/V: | Satisfactory | Comment: | | |
| Corrective Action: | | | | Corrective Date: |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| | | | | |
|-------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| | | | |
|-------------------|--|-----------------|--|
| Corrective Action | | Corrective Date | |
| Comment | | | |

| | | | | | |
|------------------------|-----------------------------|-----------------------------------|---------------------|-----------------------|--|
| Facilities: | | <input type="checkbox"/> New Tank | | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS | |
| PRODUCED WATER | 2 | <50 BBLS | BV CONCRETE | 40.240260,-104.856220 | |
| S/U/V: | Satisfactory | | Comment: 48 bbls | | |
| Corrective Action: | | | | Corrective Date: | |
| Paint | | | | | |
| Condition | | | | | |
| Other (Content) _____ | | | | | |
| Other (Capacity) _____ | | | | | |
| Other (Type) _____ | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |
| Venting: | | | | | |
| Yes/No | | Comment | | | |
| NO | | | | | |
| Flaring: | | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date | |
| | | | | | |

Predrill

Location ID: 250325

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 250325 Type: WELL API Number: 123-18128 Status: PR Insp. Status: FR

Producing Well

Comment: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

Lat _____

Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? PassProduction areas have been stabilized? Pass Segregated soils have been replaced? _____**RESTORATION AND REVEGETATION**Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Inspector Name: JOHNSON, RANDELL

Comment:

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started:

Date Final Reclamation Completed:

Final Land Use:

Reminder:

Comment:

Well plugged

Pit mouse/rat holes, cellars backfilled

Debris removed

No disturbance /Location never built

Access Roads Regraded

Contoured

Culverts removed

Gravel removed

Location and associated production facilities reclaimed

Locations, facilities, roads, recontoured

Compaction alleviation

Dust and erosion control

Non cropland: Revegetated 80%

Cropland: perennial forage

Weeds present

Subsidence

Comment:

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|------------|
| Gravel | Pass | Gravel | Pass | | | |
| Compaction | Pass | Compaction | Pass | | | |
| Other | Pass | Other | Pass | | | Vegetation |

S/U/V: Satisfactory

Corrective Date:

Comment:

CA:

Pits: ☐ NO SURFACE INDICATION OF PIT