

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:
11/07/2013

Document Number:
671100480

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

| | | | | | |
|---------------------|---------------|---------------|----------------------|--------------------|--------------------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | <input type="checkbox"/> |
| | <u>422260</u> | <u>422259</u> | <u>MONTOYA, JOHN</u> | 2A Doc Num: | |

Operator Information:

OGCC Operator Number: _____

Name of Operator: NOBLE ENERGY INC

Address: 1625 BROADWAY STE 2200

City: DENVER State: CO Zip: 80202

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|--------------|------------------------------|------------|
| Fogel, H | 970-304-5168 | HFogel@nobleenergyinc.com | regulatory |
| ELLSWORTH, STUART | | stuart.ellsworth@state.co.us | |
| Pavelka, Linda | 303-506-4592 | LPavelka@nobleenergyinc.com | |

Compliance Summary:

QtrQtr: NWSW Sec: 31 Twp: 5N Range: 65W

Inspector Comment:

FLOOD DAMAGE HAS BEEN REPAIRED

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|-------------------------------------|
| 422260 | WELL | PR | 05/01/2012 | GW | 123-33216 | SYLVESTER F 31-33 | FR | <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: <u>1</u> | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Signs/Marker:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|----------------------|-----------------------------|---------|-------------------|---------|
| CONTAINERS | Satisfactory | | | |
| BATTERY | Satisfactory | | | |
| WELLHEAD | Satisfactory | | | |
| TANK LABELS/PLACARDS | Satisfactory | | | |

Inspector Name: MONTOYA, JOHN

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|--|------|--------|-------------------|---------|
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

Fencing/:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|----------|-----------------------------|---------|-------------------|---------|
| WELLHEAD | Satisfactory | | | |

Equipment:

| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|-----------------------------|---|-----------------------------|---------|-------------------|---------|
| Bird Protectors | 5 | Satisfactory | | | |
| Emission Control Device | 1 | Satisfactory | | | |
| Gas Meter Run | 4 | Satisfactory | | | |
| Horizontal Heated Separator | 4 | Satisfactory | | | |
| Plunger Lift | 1 | Satisfactory | | | |

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|----------------|---|-----------|---------------------|--------|
| PRODUCED WATER | 4 | <100 BBLS | CONCRETE SUMP/VAULT | , |

S/U/V: Satisfactory Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

| | |
|-----------|-----------------|
| Condition | <u>Adequate</u> |
|-----------|-----------------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent | Base Sufficient | Adequate |

Corrective Action _____ Corrective Date _____

Comment _____

| | | | | | |
|--------------------|-----------------------------|-----------------------------------|---------------------|-----------------------|--|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | | |
| Contents | # | Capacity | Type | SE GPS | |
| CRUDE OIL | 4 | 300 BBLS | STEEL AST | 40.211540,-104.429250 | |
| S/U/V: | Satisfactory | Comment: | | | |
| Corrective Action: | | | | Corrective Date: | |
| Paint | | | | | |
| Condition | Adequate | | | | |
| Other (Content) | _____ | | | | |
| Other (Capacity) | _____ | | | | |
| Other (Type) | _____ | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |
| Venting: | | | | | |
| Yes/No | Comment | | | | |
| NO | | | | | |
| Flaring: | | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date | |
| Ignitor/Combustor | Satisfactory | | | | |

Predrill

Location ID: 422260

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 422260 Type: WELL API Number: 123-33216 Status: PR Insp. Status: FR

Producing Well

Comment: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/U/V: _____ Corrective Date: _____

Comment:

CA:

Pits: NO SURFACE INDICATION OF PIT