

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

11/14/2013

Document Number:

600000287

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection
	<u>248147</u>	<u>328400</u>	<u>JOHNSON, RANDELL</u>	<input type="checkbox"/> 2A Doc Num: _____

Operator Information:

OGCC Operator Number:

Name of Operator: KERR-MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Kilcrease, Keith	970-506-5926	keith.kilcrease@anadarko.com	Production Superintendent
Avant, Paul	O:720-929-6457, C:720-273-2688	paul.avant@anadarko.com	Rockies Regulatory Affairs

Compliance Summary:QtrQtr: SESE Sec: 25 Twp: 3N Range: 67W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/09/2012	667600523	PR	PR	Satisfactory			No
02/01/2007	200106720	PR	PR	Satisfactory		Pass	No
05/05/1999	500172917	PR	PR				
11/24/1998	500172916	PR	PR			Pass	No
01/12/1995	500172915						
06/08/1994	500172914		PR			Pass	No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248147	WELL	PR	06/14/1993	GW	123-15945	MAGNESS 44-25A	FR <input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
BATTERY	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	Pipe fencing		

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gas Meter Run	1	Satisfactory	Check meter/SE corner of berm around meter runs and separator 40.19024, - 104.83184		
Gas Meter Run	1	Satisfactory	Pipeline meter/SE corner of berm around meter runs and separator 40.19024, - 104.83184		
Plunger Lift	1	Satisfactory	SE corner of fence around wellhead 40.18996, - 104.83253		
Horizontal Heated Separator	1	Satisfactory	SE corner of berm around meter runs and separator 40.19024, - 104.83184		

Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	1	<50 BBLS	PBV CONCRETE	40.190390,-104.832080	
S/U/V:	Satisfactory		Comment: 43 bbls		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition					
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST	40.190390,-104.832080	
S/U/V:	Satisfactory		Comment:		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
<u>Venting:</u>					
Yes/No		Comment			
NO					
<u>Flaring:</u>					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

Predrill

Location ID: 248147

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 248147 Type: WELL API Number: 123-15945 Status: PR Insp. Status: FR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

S/V: _____ CA Date: _____

CA: _____

Comment: SI

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: JOHNSON, RANDELL

Comment: <input style="width: 700px;" type="text"/>			
Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
Water Well:			
DWR Receipt Num: _____		Owner Name: _____	GPS : _____
Lat _____		Long _____	
Field Parameters:			
<input style="width: 300px;" type="text"/>			
Sample Location: <input style="width: 400px;" type="text"/>			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____	Wildlife Protection Devices (fired vessels): _____		

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____	Date Interim Reclamation Completed: _____
Land Use: _____	
Comment: <input style="width: 750px;" type="text"/>	
1003a. Debris removed? <u>Pass</u> CM _____	
CA _____	CA Date _____
Waste Material Onsite? <u>Pass</u> CM _____	
CA _____	CA Date _____
Unused or unneeded equipment onsite? <u>Pass</u> CM _____	
CA _____	CA Date _____
Pit, cellars, rat holes and other bores closed? <u>Pass</u> CM _____	
CA _____	CA Date _____
Guy line anchors removed? <u>Pass</u> CM _____	
CA _____	CA Date _____
Guy line anchors marked? _____ CM _____	
CA _____	CA Date _____
1003b. Area no longer in use? <u>Pass</u> Production areas stabilized ? <u>Pass</u>	
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____	
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>Pass</u>	
Production areas have been stabilized? <u>Pass</u>	Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____	Recontoured _____	Perennial forage re-established _____
-------------------------	-------------------	---------------------------------------

Inspector Name: JOHNSON, RANDELL

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			Vegetation
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT