FORM INSP Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109

FIELD INSPECTION FORM

DE	ET	OE	ES

Inspection Date: 11/20/2013

Document Number: 673500161

Overall Inspection: Satisfactory

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection ☐
	89344	316166	Covington, Dave	2A Doc Num:

Operator Information:

OGCC Operator Number:

Name of Operator: ENCANA OIL & GAS (USA) INC

Address: 792 BUCKHORN DR

City: RIFLE State: CO Zip: 81650

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	
KELLERBY, SHAUN		shaun.kellerby@state.co.us	

Compliance Summary:

QtrQtr: NWSW Sec: 14 Twp: 2S Range: 103W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/12/2000	200006887	PR	PR	Satisfactory		Pass	No

Inspector Comment:

Wellhead, meter house, small produced H2O tank

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
89344	WELL	PR	06/01/2002	GW	103-09937	LOWER HORSE DRAW UNIT 2170	PR	☒
267013	WELL	DA	08/30/2003	GW	103-10288	LHDU 2247	DA	☐

Equipment:

Location Inventory

Special Purpose Pits:		Drilling Pits:		Wells:		Production Pits:	
Condensate Tanks:		Water Tanks:		Separators:		Electric Motors:	
Gas or Diesel Mortors:		Cavity Pumps:		LACT Unit:		Pump Jacks:	
Electric Generators:		Gas Pipeline:		Oil Pipeline:		Water Pipeline:	
Gas Compressors:		VOC Combustor:		Oil Tanks:		Dehydrator Units:	
Multi-Well Pits:		Pigging Station:		Flare:		Fuel Tanks:	

Location

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Main	Satisfactory			

Inspector Name: Covington, Dave

Access	Satisfactory			

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment:

Corrective Action:

Spills:				
Type	Area	Volume	Corrective action	CA Date

☐ Multilple Spills and Releases?

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK BATTERY	Satisfactory	Stock panels around small tank		

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Plunger Lift	1	Satisfactory			
Deadman # & Marked	4	Satisfactory			
Gas Meter Run	1	Satisfactory			

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<50 BBLS	STEEL AST	39.872720,-108.930560

S/U/V:	Satisfactory	Comment:	
Corrective Action:		Corrective Date:	

Paint

Condition	Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate

Corrective Action		Corrective Date	
Comment			

Venting:	
Yes/No	Comment
NO	

Inspector Name: Covington, Dave

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 89344

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 89344 Type: WELL API Number: 103-09937 Status: PR Insp. Status: PR

Producing Well

Comment: Wellhead, meter house, small produced H2O tank

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: Covington, Dave

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well: Lat Long

DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? Pass CM

CA CA Date

Waste Material Onsite? Pass CM

CA CA Date

Unused or unneeded equipment onsite? Pass CM

CA CA Date

Pit, cellars, rat holes and other bores closed? CM

CA CA Date

Guy line anchors removed? CM

CA CA Date

Guy line anchors marked? Pass CM

CA CA Date

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped?

1003d. Drilling pit closed? Subsidence over on drill pit?

Cuttings management:

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?

Production areas have been stabilized? Segregated soils have been replaced?

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Recontoured Perennial forage re-established

Inspector Name: Covington, Dave

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment:

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					

S/U/V: Satisfactory Corrective Date: _____

Comment:

CA:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
673500161	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3233008