

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
11/25/2013

Document Number:
673500190

Overall Inspection:
Unsatisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>229263</u>	<u>314687</u>	<u>Covington, Dave</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: _____

Name of Operator: CALCO DBA CALLISTER CO

Address: 2005 300 WEST

City: SALT LAKE CITY State: UT Zip: 84115

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Jan Callister		jec@apexoilventures.com	
KELLERBY, SHAUN		shaun.kellerby@state.co.us	

Compliance Summary:

QtrQtr: NENE Sec: 8 Twp: 1N Range: 101W

Inspector Comment:

Wellhead and pump Jack that had been moved off of its pad.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229263	WELL	SI	01/15/2013	GW	103-06358	CALLISTER-GOVERNMENT 4	TA <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			
Main	Satisfactory			

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Unsatisfactory	needs sign	Install sign to comply with rule 210.	12/31/2013

Inspector Name: Covington, Dave

Emergency Contact Number: (S/U/V) Unsatisfactory

Corrective Date: 12/31/2013

Comment: needs sign

Corrective Action: put contact information on wellhead

Good Housekeeping:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
DEBRIS	Unsatisfactory	pipe and other metal on location	remove excess material.	12/31/2013

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Pump Jack	1	Unsatisfactory	it has been moved off of well pad	If its not going to be used it needs to be taken away.	03/28/2014

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
------	-----------------------------	---------	-------------------	---------

Predrill

Location ID: 229263

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 229263 Type: WELL API Number: 103-06358 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

S/V: Unsatisfactory CA Date: 06/30/2014

CA: Well must be either: 1) Put on production or 2) Per COGCC Rule 326.b.(1) a mechanical integrity test shall be performed on each temporarily abandoned well within thirty (30) days of the date the well becomes incapable of production or 3) Be properly plugged and abandoned. 4) A sundry requesting continued temporarily abandoned status should be submitted to Bob Koehler at the COGCC within thirty (30) days of receipt of this report - the sundry should detail the plan for the future operation of the well and the way the well is closed to the atmosphere. Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report.

Comment: Pump Jack has been moved off of pad

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: _____
Comment: _____
1003a. Debris removed? Pass CM _____ CA _____ CA Date _____
Waste Material Onsite? Pass CM _____ CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____ CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____ CA _____ CA Date _____
Guy line anchors removed? _____ CM _____ CA _____ CA Date _____
Guy line anchors marked? _____ CM _____ CA _____ CA Date _____
1003b. Area no longer in use? Pass Production areas stabilized? Pass
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT