

Well:	HMU 6-15D
Pad:	J6SEB
API No:	0504521944
Permit No:	

Bradenhead Pressure Report Following Primary Cement Job

Date Cemented:	09/15/2013
Plug Bumped:	yes

Annular Fluid Level After Job (Static or Falling?):	static	
If falling, barrels of mud added until stabilized:	n/a	barrels

WOC Time:	6 hrs
Bond Log Run:	Temp Log & CBL

Casing Slips Set:	yes
-------------------	-----

Brandenhead Pressures

6 hrs:	0	psig
12 hrs:	0	psig
24 hrs:	0	psig
48 hrs:	0	psig
72 hrs:	0	psig

Comments

100% return during the cement job. The annulus stayed full and static. A Temp Log was run 6hrs after CIP. A CBL was performed when the rig moved off the pad.