

FORM INSP <small>Rev 05/11</small>	State of Colorado Oil and Gas Conservation Commission <small>1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109</small>		DE	ET	OE	ES
						Inspection Date: <u>12/09/2013</u>
						Document Number: <u>663902472</u>
						Overall Inspection: <u>Satisfactory</u>
Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection <input type="checkbox"/>		
<u>334920</u>	<u>334920</u>	<u>334920</u>	<u>LONGWORTH, MIKE</u>	2A Doc Num: _____		

Operator Information:

OGCC Operator Number: _____

Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLC

Address: 1001 17TH STREET - SUITE #1200

City: DENVER State: CO Zip: 80202

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Gardner, Michael	970/285-9377 ext. 2760	Michael.Gardner@WPXEnergy.com	Principal Environmental Specialist
Moss, Brad	(970) 285-9377	Brad.Moss@WPXEnergy.com	Production foreman
Kellerby, Shaun		shaun.kellerby@state.co.us	

Compliance Summary:

QtrQtr: NWNE Sec: 6 Twp: 7S Range: 95W

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
270608	WELL	PR	12/04/2003	GW	045-09567	PA 531-6	PR	<input checked="" type="checkbox"/>
270609	WELL	PR	07/16/2004	GW	045-09568	PA 31-6	PR	<input checked="" type="checkbox"/>
270610	WELL	PR	07/12/2004	GW	045-09569	PA 331-6	PR	<input checked="" type="checkbox"/>
270611	WELL	PR	07/21/2004	GW	045-09570	PA 431-6	PR	<input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	Snow packed / plowed		

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	Satisfactory			
BATTERY	Satisfactory			
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK BATTERY	Satisfactory			
WELLHEAD	Satisfactory			
SEPARATOR	Satisfactory			

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Plunger Lift	4	Satisfactory			

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST	39.473750,108.037610

S/U/V: Satisfactory Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

Condition	<u>Adequate</u>
-----------	-----------------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	<u>Adequate</u>			

Corrective Action _____ Corrective Date _____

Comment Snow covered

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	1	200 BBLS	STEEL AST	,	
S/U/V:	Satisfactory		Comment:		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Corrective Action				Corrective Date	
Comment					

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST	,	
S/U/V:	Satisfactory		Comment:		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Corrective Action				Corrective Date	
Comment					

Venting:				
Yes/No	Comment			
YES	Bradens venting			
Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 334920

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 270608 Type: WELL API Number: 045-09567 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 270609 Type: WELL API Number: 045-09568 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 270610 Type: WELL API Number: 045-09569 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 270611 Type: WELL API Number: 045-09570 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS: Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):
Comment:
Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:
Land Use:
Comment: Location snow covered
1003a. Debris removed? Pass CM CA Date
Waste Material Onsite? Pass CM CA Date
Unused or unneeded equipment onsite? Pass CM CA Date
Pit, cellars, rat holes and other bores closed? CM CA Date
Guy line anchors removed? CM CA Date
Guy line anchors marked? CM CA Date
1003b. Area no longer in use? Production areas stabilized ?

1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment:

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: Road and location snow covered.

CA:

Pits: NO SURFACE INDICATION OF PIT