

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



|    |    |    |    |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:  
12/16/2013

Document Number:  
600000435

Overall Inspection:  
Satisfactory

**FIELD INSPECTION FORM**

|                     |               |               |                         |                    |                          |
|---------------------|---------------|---------------|-------------------------|--------------------|--------------------------|
| Location Identifier | Facility ID   | Loc ID        | Inspector Name:         | On-Site Inspection | <input type="checkbox"/> |
|                     | <u>202618</u> | <u>320100</u> | <u>JOHNSON, RANDELL</u> | 2A Doc Num:        |                          |

**Operator Information:**

OGCC Operator Number: \_\_\_\_\_

Name of Operator: BARRETT CORPORATION\* BILL

Address: 1099 18TH ST STE 2300

City: DENVER State: CO Zip: 80202

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name       | Phone        | Email                           | Comment                             |
|--------------------|--------------|---------------------------------|-------------------------------------|
| Zavadil, Duane     | 303-293-9100 | dzavadil@billbarrettcorp.com    | Government and Regulatory Affairs   |
| Pennington, David  | 970-230-0435 | dpennington@billbarrettcorp.com | Production Foreman - Greeley Office |
| Singleton, John Ed | 970-353-0407 | jsingleton@billbarrettcorp.com  | Area Superintendent                 |

**Compliance Summary:**

QtrQtr: SENV Sec: 7 Twp: 1S Range: 67W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 01/02/2008 | 200128725 | PR         | PR          | Unsatisfactory               |          |                | Yes             |
| 10/30/2001 | 1099731   | CO         | PR          | Satisfactory                 |          |                |                 |

**Inspector Comment:**

\_\_\_\_\_

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status                            |
|-------------|------|--------|-------------|------------|-----------|---------------|--|
| 102277      | PIT  |        | 09/23/1999  |            | -         | SAUVAGE 3     | <input type="checkbox"/>               |
| 202618      | WELL | SI     | 04/11/2013  | GW         | 001-08023 | SAUVAGE 3     | SI <input checked="" type="checkbox"/> |

**Equipment:**

Location Inventory

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

\_\_\_\_\_

| <b>Signs/Marker:</b> |                             |         |                   |         |
|----------------------|-----------------------------|---------|-------------------|---------|
| Type                 | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| TANK LABELS/PLACARDS | Satisfactory                |         |                   |         |
| BATTERY              | Satisfactory                |         |                   |         |
| WELLHEAD             | Satisfactory                |         |                   |         |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

| <b>Spills:</b>   |      |        |                   |         |
|--|------|--------|-------------------|---------|
| Type   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

| <b>Equipment:</b>           |   |                             |         |                   |         |
|-----------------------------|---|-----------------------------|---------|-------------------|---------|
| Type                        | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Emission Control Device     | 1 | Satisfactory                |         |                   |         |
| Gas Meter Run               | 1 | Satisfactory                |         |                   |         |
| Horizontal Heated Separator | 1 | Satisfactory                |         |                   |         |

| <b>Facilities:</b>                |              |                |                |                        |  |
|-----------------------------------|--------------|----------------|----------------|------------------------|--|
| <input type="checkbox"/> New Tank |              | Tank ID: _____ |                |                        |  |
| Contents                          | #            | Capacity       | Type           | SE GPS                 |  |
| CRUDE OIL                         | 1            | 300 BBLS       | STEEL AST      | 39.985880,-104.932400  |  |
| S/U/V:                            | Satisfactory |                | Comment: _____ |                        |  |
| Corrective Action: _____          |              |                |                | Corrective Date: _____ |  |

**Paint**

|           |          |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

| <b>Berms</b>      |          |                     |                     |                 |
|-------------------|----------|---------------------|---------------------|-----------------|
| Type              | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance     |
| Earth             | Adequate | Walls Sufficient    | Base Sufficient     | Adequate        |
| Corrective Action |          |                     |                     | Corrective Date |
| Comment           |          |                     |                     |                 |

|                    |                             |                                   |                     |                       |  |
|--------------------|-----------------------------|-----------------------------------|---------------------|-----------------------|--|
| <b>Facilities:</b> |                             | <input type="checkbox"/> New Tank | Tank ID: _____      |                       |  |
| Contents           | #                           | Capacity                          | Type                | SE GPS                |  |
| PRODUCED WATER     | 1                           | 100 BBLS                          | PBV FIBERGLASS      | 39.985880,-104.932400 |  |
| S/U/V:             | Satisfactory                | Comment:                          |                     |                       |  |
| Corrective Action: |                             |                                   |                     | Corrective Date:      |  |
| <b>Paint</b>       |                             |                                   |                     |                       |  |
| Condition          | Adequate                    |                                   |                     |                       |  |
| Other (Content)    | _____                       |                                   |                     |                       |  |
| Other (Capacity)   | _____                       |                                   |                     |                       |  |
| Other (Type)       | _____                       |                                   |                     |                       |  |
| <b>Berms</b>       |                             |                                   |                     |                       |  |
| Type               | Capacity                    | Permeability (Wall)               | Permeability (Base) | Maintenance           |  |
| Earth              | Adequate                    | Walls Sufficient                  | Base Sufficient     | Adequate              |  |
| Corrective Action  |                             |                                   |                     | Corrective Date       |  |
| Comment            |                             |                                   |                     |                       |  |
| <b>Venting:</b>    |                             |                                   |                     |                       |  |
| Yes/No             | Comment                     |                                   |                     |                       |  |
| NO                 |                             |                                   |                     |                       |  |
| <b>Flaring:</b>    |                             |                                   |                     |                       |  |
| Type               | Satisfactory/Unsatisfactory | Comment                           | Corrective Action   | CA Date               |  |
|                    |                             |                                   |                     |                       |  |

**Predrill**

Location ID: 202618

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/U/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Facility**

Facility ID: 202618 Type: WELL API Number: 001-08023 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

S/V: \_\_\_\_\_ CA Date: \_\_\_\_\_

CA: \_\_\_\_\_

Comment: SI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:** \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:** \_\_\_\_\_

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? In Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_ P \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation Pass

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

S/U/V: Satisfactory \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT