

Predrill

Location ID: 234894

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/UV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/UV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/UV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 234894 Type: WELL API Number: 121-07036 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

- 1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
- Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
- Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
- Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
- Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
- Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Inspector Name: Sherman, Susan

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/U/V: _____ Corrective Date: _____

Comment: Operator working with farmer to control sediment transfer from pit berms to field.

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 673700403 | ARK Trust Treater | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3248008 |
| 673700404 | ARK Trust Tank Sign | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3248009 |
| 673700405 | ARK Trust Propane Label | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3248010 |
| 673700406 | ARK Trust Battery Sign | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3248011 |
| 673700407 | ARK Trust Battery Tank Sign 2 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3248012 |