

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:

12/20/2013

Document Number:

663902539

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 335642 | 335642 | LONGWORTH, MIKE | <input type="checkbox"/> | |

Operator Information:

OGCC Operator Number:

Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|------------------------------|---------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| Insp., General | 970-285-2665 | cogcc.inspections@encana.com | |
| YOKLEY, BILL | | bill.yokley@state.co.us | |

Compliance Summary:

| QtrQtr: | <u>SENE</u> | Sec: | <u>26</u> | Twp: | <u>5S</u> | Range: | <u>96W</u> |
|------------|-------------|------------|-------------|------------------------------|-----------|----------------|-----------------|
| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
| 05/30/2012 | 663800367 | | | Satisfactory | | | No |

Inspector Comment:No evidence of the AL wells ever being drilled.**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|-------------------------------------|
| 280184 | WELL | PR | 12/01/2010 | GW | 045-11214 | N PARACHUTE WF09B-26H26A596 | PR | <input type="checkbox"/> |
| 280469 | WELL | PR | 04/10/2006 | GW | 045-11261 | N PARACHUTE WF08D-26H26A596 | PR | <input type="checkbox"/> |
| 296238 | WELL | AL | 06/26/2012 | LO | 045-15954 | ENCANA RPW 333-26-596 | AL | <input checked="" type="checkbox"/> |
| 296240 | WELL | AL | 06/26/2012 | LO | 045-15955 | ENCANA RPW 334-26-596 | AL | <input checked="" type="checkbox"/> |
| 296241 | WELL | AL | 06/26/2012 | LO | 045-15956 | ENCANA RPW 432-26-596 | AL | <input checked="" type="checkbox"/> |
| 296242 | WELL | AL | 06/26/2012 | LO | 045-15957 | ENCANA RPW 443-26-596 | AL | <input checked="" type="checkbox"/> |
| 296243 | WELL | AL | 06/26/2012 | LO | 045-15958 | ENCANA RPW 42-26-596 | AL | <input checked="" type="checkbox"/> |
| 296244 | WELL | AL | 06/26/2012 | LO | 045-15959 | ENCANA RPW 533-26-596 | AL | <input checked="" type="checkbox"/> |
| 296245 | WELL | AL | 06/26/2012 | LO | 045-15960 | ENCANA RPW 34-26-596 | AL | <input checked="" type="checkbox"/> |

Inspector Name: LONGWORTH, MIKE

| | | | | | | | | |
|--------|------|----|------------|----|-----------|-----------------------|----|---|
| 296246 | WELL | AL | 06/26/2012 | LO | 045-15961 | ENCANA RPW 434-26-596 | AL | X |
| 296247 | WELL | AL | 06/26/2012 | LO | 045-15962 | ENCANA RPW 534-26-596 | AL | X |
| 296248 | WELL | AL | 06/26/2012 | LO | 045-15963 | ENCANA RPW 543-26-596 | AL | X |
| 296249 | WELL | AL | 06/26/2012 | LO | 045-15964 | ENCANA RPW 43-26-596 | AL | X |
| 296250 | WELL | AL | 06/26/2012 | LO | 045-15965 | ENCANA RPW 433-26-596 | AL | X |
| 296251 | WELL | AL | 06/26/2012 | LO | 045-15966 | ENCANA RPW 32-26-596 | AL | X |
| 296252 | WELL | AL | 06/26/2012 | LO | 045-15967 | ENCANA RPW 342-26-596 | AL | X |
| 296253 | WELL | AL | 06/26/2012 | LO | 045-15968 | ENCANA RPW 332-26-596 | AL | X |
| 296254 | WELL | AL | 06/26/2012 | LO | 045-15969 | ENCANA RPW 33-26-596 | AL | X |
| 296255 | WELL | AL | 06/26/2012 | LO | 045-15970 | ENCANA RPW 341-26-596 | AL | X |
| 296352 | WELL | AL | 06/26/2012 | LO | 045-15996 | ENCANA RPW 442-26-596 | AL | X |

Equipment:Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Emergency Contact Number: (S/U/V) _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?**Venting:**

| Yes/No | Comment |
|--------|---------|
|--------|---------|

Flaring:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|------|-----------------------------|---------|-------------------|---------|
|------|-----------------------------|---------|-------------------|---------|

Predrill

Location ID: 335642

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 296238 Type: WELL API Number: 045-15954 Status: AL Insp. Status: AL

Facility ID: 296240 Type: WELL API Number: 045-15955 Status: AL Insp. Status: AL

Facility ID: 296241 Type: WELL API Number: 045-15956 Status: AL Insp. Status: AL

Facility ID: 296242 Type: WELL API Number: 045-15957 Status: AL Insp. Status: AL

Facility ID: 296243 Type: WELL API Number: 045-15958 Status: AL Insp. Status: AL

Facility ID: 296244 Type: WELL API Number: 045-15959 Status: AL Insp. Status: AL

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 296245 | Type: WELL | API Number: 045-15960 | Status: AL | Insp. Status: AL |
| Facility ID: 296246 | Type: WELL | API Number: 045-15961 | Status: AL | Insp. Status: AL |
| Facility ID: 296247 | Type: WELL | API Number: 045-15962 | Status: AL | Insp. Status: AL |
| Facility ID: 296248 | Type: WELL | API Number: 045-15963 | Status: AL | Insp. Status: AL |
| Facility ID: 296249 | Type: WELL | API Number: 045-15964 | Status: AL | Insp. Status: AL |
| Facility ID: 296250 | Type: WELL | API Number: 045-15965 | Status: AL | Insp. Status: AL |
| Facility ID: 296251 | Type: WELL | API Number: 045-15966 | Status: AL | Insp. Status: AL |
| Facility ID: 296252 | Type: WELL | API Number: 045-15967 | Status: AL | Insp. Status: AL |
| Facility ID: 296253 | Type: WELL | API Number: 045-15968 | Status: AL | Insp. Status: AL |
| Facility ID: 296254 | Type: WELL | API Number: 045-15969 | Status: AL | Insp. Status: AL |
| Facility ID: 296255 | Type: WELL | API Number: 045-15970 | Status: AL | Insp. Status: AL |
| Facility ID: 296352 | Type: WELL | API Number: 045-15996 | Status: AL | Insp. Status: AL |

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Inspector Name: LONGWORTH, MIKE

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Inspector Name: LONGWORTH, MIKE

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT