

Inspector Name: Carlile, Craig

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

12/20/2013

Document Number:

674000168

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|---------------|---------------|-----------------------|--------------------|--|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | |
| | <u>272015</u> | <u>332333</u> | <u>Carlile, Craig</u> | 2A Doc Num: | |

Operator Information:

OGCC Operator Number:

Name of Operator: KERR-MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|----------------|--------------------------|-----------------|
| Precup, Jim | | james.precup@state.co.us | |
| Avant, Paul | (720) 929-6457 | Paul.Avant@Anadarko.com | All Inspections |

Compliance Summary:QtrQtr: NESW Sec: 10 Twp: 3N Range: 66W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 02/14/2006 | 200088513 | PR | PR | Satisfactory | | Pass | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|-------------------------------------|
| 272015 | WELL | PR | 04/30/2008 | GW | 123-22163 | MORNING FRESH 11-10 | PR | <input checked="" type="checkbox"/> |

Equipment:**Location Inventory**

| | | | |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Signs/Marker: | | | | |
|----------------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD | Satisfactory | | | |

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Inspector Name: Carlile, Craig

Corrective Action:

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

Fencing/:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|------|-----------------------------|---------|-------------------|---------|
|------|-----------------------------|---------|-------------------|---------|

| | | | | |
|----------|--------------|------|--|--|
| WELLHEAD | Satisfactory | Pipe | | |
|----------|--------------|------|--|--|

Equipment:

| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|------|---|-----------------------------|---------|-------------------|---------|
|------|---|-----------------------------|---------|-------------------|---------|

| | | | | | |
|--------------|---|--------------|--|--|--|
| Plunger Lift | 1 | Satisfactory | | | |
|--------------|---|--------------|--|--|--|

Facilities:

☐ New Tank

Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|----------|---|----------|------|--------|
| | | | | , |

| | | | |
|--------|--|----------|---------------------------|
| S/U/V: | | Comment: | Battery Location # 328480 |
|--------|--|----------|---------------------------|

| | | | |
|--------------------|--|------------------|--|
| Corrective Action: | | Corrective Date: | |
|--------------------|--|------------------|--|

Paint

| | |
|-----------|--|
| Condition | |
|-----------|--|

Other (Content)

Other (Capacity)

Other (Type)

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

| | | | |
|-------------------|--|-----------------|--|
| Corrective Action | | Corrective Date | |
|-------------------|--|-----------------|--|

| | |
|---------|--|
| Comment | |
|---------|--|

Venting:

| | |
|--------|---------|
| Yes/No | Comment |
|--------|---------|

| | |
|--|--|
| | |
|--|--|

Flaring:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|------|-----------------------------|---------|-------------------|---------|
|------|-----------------------------|---------|-------------------|---------|

| | | | | |
|--|--|--|--|--|
| | | | | |
|--|--|--|--|--|

Predrill

Location ID: 272015

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 272015 Type: WELL API Number: 123-22163 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Inspector Name: Carlile, Craig

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Inspector Name: Carlile, Craig

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started:

Date Final Reclamation Completed:

Final Land Use:

Reminder:

Comment:

Well plugged

Pit mouse/rat holes, cellars backfilled

Debris removed

No disturbance /Location never built

Access Roads

Regraded

Contoured

Culverts removed

Gravel removed

Location and associated production facilities reclaimed

Locations, facilities, roads, recontoured

Compaction alleviation

Dust and erosion control

Non cropland: Revegetated 80%

Cropland: perennial forage

Weeds present

Subsidence

Comment:

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|----------------------|----------------------|-------------------------|-----------------------|----------------------|--------------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> | <input type="text"/> |

S/U/V:

Corrective Date:

Comment:

CA:

Pits: ☐ NO SURFACE INDICATION OF PIT