

FORM INSP Rev 05/11	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		DE ET OE ES
FIELD INSPECTION FORM			Inspection Date: <u>12/23/2013</u>
Location Identifier: <u>207690</u> Facility ID: <u>321654</u> Inspector Name: <u>QUINT, CRAIG</u> On-Site Inspection: <input type="checkbox"/>			Document Number: <u>668601877</u>
2A Doc Num: _____			Overall Inspection: <u>Satisfactory</u>

Operator Information:

OGCC Operator Number: _____

Name of Operator: WILLIFORD ENERGY COMPANY

Address: 6100 S YALE AVE STE 2000

City: TULSA State: OK Zip: 74136

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Hubbard, Corky	806-658-9758 off	whubbard@willifordenergy.com	806-435-0529 cell

Compliance Summary:

QtrQtr: NWNE Sec: 32 Twp: 13S Range: 48W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/29/2013	668600280	PR	PR	Satisfactory			No
01/10/2012	663900385	PR	PR	Satisfactory	P		No
05/07/2010	200247923	PR	SI	Satisfactory			No
12/08/2008	200200434	PR	SI	Satisfactory			No
08/15/2007	200116869	PR	SI	Satisfactory			No
07/21/2006	200094683	PR	PR	Satisfactory		Pass	No
12/17/2001	200022483	PR	PR	Satisfactory		Pass	No
12/13/1999	500139039	PR	PR			Pass	No
12/08/1997	500139038	PR	PR			Fail	Yes
04/18/1996	500139037	PR	PR			Pass	No
11/18/1994	500139036		PR				

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207690	WELL	PR	10/19/1986	OW	017-06625	RHOADES 5-32	PR <input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	DIRT ROAD THROUGH PASTURE.		

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	LEASE SIGN MOUNTED ON UNIT		

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	STEEL PANELS AROUND WELLHEAD AND CATHOTIC RECTIFIER.		

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
			CENTRALIZED BATTERY	38.877860,-102.814420	
S/U/V:	Satisfactory	Comment:	CENTRAL TANK BATTERY F/(RHOADES 5-4, 5-32, 5 7-32, 6-32, 13-31 #2, 44-31 #5) 3280' W		
Corrective Action:				Corrective Date:	
Paint					
Condition					
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Corrective Action				Corrective Date	
Comment					
Venting:					
Yes/No	Comment				
NO					
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

Predrill

Location ID: 207690

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 207690 Type: WELL API Number: 017-06625 Status: PR Insp. Status: PR

Producing Well

Comment: PRODUCING, CENTRAL TANK BATTERY F/(RHOADES 5-4, 5-32, 5 7-32, 6-32, 13-31 #2, 44-31 #5) 3280' W @ 38.877860,-102.814420

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:
Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: _____
Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland
Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland
Top soil replaced _____ Recontoured _____ 80% Revegetation _____

Inspector Name: QUINT, CRAIG

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT