

Inspector Name: Sherman, Susan

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

12/26/2013

Document Number:

673700532

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection
	204336	320660	Sherman, Susan	<input type="checkbox"/> 2A Doc Num: _____

Operator Information:

OGCC Operator Number:

Name of Operator: BECCA OIL LLCAddress: P O BOX 1347City: CUSHING State: OK Zip: 74023

- ☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED
☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
NOTO, JOHN		noto.john@state.co.us	
Greenwood, Gina	918-225-2334	gina.beccaoil@gmail.com	

Compliance Summary:QtrQtr: NESW Sec: 6 Twp: 4S Range: 62W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/05/2005	200081271	PR	PR	Satisfactory		Pass	No
10/03/2000	896293	ES	PR	Unsatisfactory		Fail	Yes
05/26/2000	848129	ES	PR	Unsatisfactory		Fail	No
09/17/1999	845056	ES	PR	Satisfactory			No
05/13/1998	500134374	PR	PR			Fail	Yes
03/27/1998	500134373	PR	PR			Fail	Yes
11/30/1995	500134372	PR	PR			Fail	Yes
11/08/1995	500134368	PR	PR			Fail	Yes
10/12/1995	500134367	PR	PR			Fail	Yes
02/28/1995	500134366	PR	PR				

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
109608	PIT		09/23/1999		-	BILLINGS 1-6	<input type="checkbox"/>
204336	WELL	PR	12/27/2001	GW	005-06421	BILLINGS 1-6	PR <input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Inspector Name: Sherman, Susan

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
STORAGE OF SUPL		Misc containers around wellhead.		

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gas Meter Run	1	Satisfactory			
Prime Mover	1	Satisfactory	propane		
Horizontal Heater Treater	1	Satisfactory			
Pump Jack	1	Satisfactory			
Bird Protectors	1	Satisfactory			

Inspector Name: Sherman, Susan

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST	39.727230,-104.376950
S/U/V:	Satisfactory	Comment:		
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action	Corrective Date
Comment	

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	2	300 BBLS	FIBERGLASS AST	,
S/U/V:		Comment: same berm as crude oil tanks		
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action	Corrective Date
Comment	

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 204336

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 204336 Type: WELL API Number: 005-06421 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Inspector Name: Sherman, Susan

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____ Pass _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Inspector Name: Sherman, Susan

Comment: **Pass at wellhead**

Overall Interim Reclamation **Pass**

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Compaction	Pass	MHSP	Fail	
Gravel	Pass	Gravel	Pass	MHSP	Pass	

S/U/V: **Unsatisfactory** Corrective Date: **01/31/2014**

Comment: **Erosion on south side of tank battery berm. Sediment leaving site and going onto wheat field (see attached photos).
Chemical BMP at wellhead needs BMPs. Berm breached (see attached photo).**

CA: **Install BMPs**

Pits: ☐ NO SURFACE INDICATION OF PIT

Inspector Name: Sherman, Susan

Pit Type: Skimming/Settling Lined: NO Pit ID: _____ Lat: _____ Long: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Observed rill from pit going to field

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Netting:

Netting Type: Metal Grid Netting Condition: Good

Comment: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Pit (S/U/V): _____ Comment: _____

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673700570	Billings 1_6 Container BMP	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3252907
673700571	Billings 1_6 IR	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3252908
673700572	Billings 1_6 Battery Rills	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3252909
673700573	Billings 1_6 Sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3252910
673700574	Billings 1_6 Battery Rills into field	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3252911
673700575	Billings 1_6 Battery Rills into field East	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3252912
673700576	Billings 1_6 Battery Rills 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3252913
673700577	Billings 1_6 Battery sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3252914
673700578	Billings 1_6 Wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3252915