

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

12/31/2013

Document Number:

663902584

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335670	335670	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:

Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Insp., General	970-285-2665	cogcc.inspections@encana.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Compliance Summary:QtrQtr: SESW Sec: 30 Twp: 5S Range: 95W**Inspector Comment:**No evidence of 045-15199 AL well.**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
281864	WELL	PR	10/19/2006	GW	045-11551	N.PARACHUTE EF08B N30 595	PR	<input type="checkbox"/>
281866	WELL	PR	11/02/2006	GW	045-11552	N.PARACHUTE EF02B N30 595	PR	<input type="checkbox"/>
281867	WELL	PR	12/07/2005	GW	045-11553	N.PARACHUTE EF06D N30 595	PR	<input type="checkbox"/>
281868	WELL	PR	11/27/2006	GW	045-11554	N. PARACHUTE EF03B N30 595	PR	<input type="checkbox"/>
281870	WELL	PR	09/25/2006	GW	045-11555	N.PARACHUTE EF02D N30 595	PR	<input type="checkbox"/>
281884	WELL	PR	10/27/2006	GW	045-11556	N.PARACHUTE EF07B N30 595	PR	<input type="checkbox"/>
281887	WELL	PR	12/07/2005	GW	045-11557	N.PARACHUTE EF03D N30 595	PR	<input type="checkbox"/>
281888	WELL	PR	11/27/2006	GW	045-11558	N. PARACHUTE EF06B N30 595	PR	<input type="checkbox"/>
285021	PIT	AC	06/07/2006		-	NP EF07B N30 595	AC	<input type="checkbox"/>
294007	WELL	AL	02/21/2008	LO	045-15199	N.PARCHUTE EF11C-31 N30 59	AL	<input checked="" type="checkbox"/>
294008	WELL	PR	01/20/2009	GW	045-15200	N. PARACHUTE EF06C-31 N30 59	PR	<input type="checkbox"/>
294009	WELL	PR	07/06/2008	GW	045-15201	N. PARACHUTE EF02A-31 N30 59	PR	<input type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

294010	WELL	PR	07/06/2008	GW	045-15202	N. PARACHUTE EF02C-31 N30 59	PR	
294011	WELL	PR	07/24/2009	GW	045-15203	N.PRACHUTE EF07D-31 N30 59	PR	
294012	WELL	PR	01/20/2009	GW	045-15204	N. PARACHUTE EF06A-31 N30 59	PR	
294013	WELL	PR	01/12/2009	GW	045-15205	N. PARACHUTE EF03D-31 N30	PR	
294014	WELL	PR	01/20/2009	GW	045-15206	N. PARACHUTE EF03A-31 N30 59	PR	
294016	WELL	PR	01/07/2009	GW	045-15207	N.PARACHUTE EF08D-31 N30 59	PR	
294017	WELL	PR	07/06/2008	GW	045-15208	N.PARACHUTE EF08A-31 N30 59	PR	
294018	WELL	PR	07/06/2008	GW	045-15209	N.PARACHUTE EF08C-31 N30 59	PR	
294019	WELL	PR	01/06/2009	GW	045-15210	N.PARACHUTE EF07A-31 N30 59	PR	
294022	WELL	PR	01/06/2009	GW	045-15211	N. PARACHUTE EF07C-31 N30 59	PR	
294023	WELL	PR	01/20/2009	GW	045-15212	N.PARACHUTE EF11A-31 N30 59	PR	
294024	WELL	PR	01/20/2009	GW	045-15213	N.PARACHUTE EF11B-31 N30 59	PR	
294025	WELL	PR	01/06/2009	GW	045-15214	N.PARCHUTE EF10A-31 N30 59	PR	

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

LocationEmergency Contact Number: (S/U/V) _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Venting:**

Yes/No	Comment
--------	---------

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 335670

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 294007 Type: WELL API Number: 045-15199 Status: AL Insp. Status: AL

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Inspector Name: LONGWORTH, MIKE

Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	
Water Well:		
DWR Receipt Num: _____	Owner Name: _____	GPS : _____
Field Parameters:		
Sample Location: _____		
Emission Control Burner (ECB): _____		
Comment: _____		
Pilot: _____	Wildlife Protection Devices (fired vessels): _____	

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____	Date Interim Reclamation Completed: _____
Land Use: _____	
Comment: _____	
1003a. Debris removed? _____ CM _____	
CA _____	CA Date _____
Waste Material Onsite? _____ CM _____	
CA _____	CA Date _____
Unused or unneeded equipment onsite? _____ CM _____	
CA _____	CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____	
CA _____	CA Date _____
Guy line anchors removed? _____ CM _____	
CA _____	CA Date _____
Guy line anchors marked? _____ CM _____	
CA _____	CA Date _____
1003b. Area no longer in use? _____	
Production areas stabilized ? _____	
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____	
Subsidence over on drill pit? _____	
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____	
Production areas have been stabilized? _____	
Segregated soils have been replaced? _____	
RESTORATION AND REVEGETATION	
<u>Cropland</u>	
Top soil replaced _____	Recontoured _____
Perennial forage re-established _____	
<u>Non-Cropland</u>	
Top soil replaced _____	Recontoured _____
80% Revegetation _____	

Inspector Name: LONGWORTH, MIKE

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	285021	1433412	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
663902584	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3254784