FORM
27
Rev 6/99

Click here to reset form

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303)894-2100 Fax:(303)894-2109

FOR OGCC USE ONLY

OGCC Employee:
☐ Spill ☐ Complaint
☐ Inspection ☐ NOAV
Tracking No:

SITE INVESTIGATION AND REMEDIATION WORKPLAN

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. Form 27 is intended to be used whenever possible. Additional documentation will be required when large volumes of soil and groundwater have been impacted or involve large facilities with multiple source areas. See Rule 910. Attach as many pages as needed to fully describe the proposed work.

CAUSE OF CONDITION BEING INVESTIGATED AND REMEDIATED

☑ Spill or Release ☐ Plug & Abandon ☐ Central Facility Closure ☐ Site/Facility Closure ☐ Other (describe): Remed #7539

OGCC Operator Number: 10282
Name of Operator: Ephphatha, LLC
Address: 3004 Hwy 238
City: Jacksonville State: OR Zip: 97530

Contact Name and Telephone:
Cory Sullins
No: 310-901-1996
Fax: csullins03@yahoo.com

API Number: 05-107-06175
County: Routt
Facility Name: Dry Creek UT HD 31
Facility Number: 232760
Well Name: Dry Creek UT HD 31
Well Number: 1A
Location: (QtrQtr, Sec, Twp, Rng, Meridian): NENE, 31, 6N, 88W, 6th
Latitude: 40.43895N Longitude: 107.298851W

TECHNICAL CONDITIONS

Type of Waste Causing Impact (crude oil, condensate, produced water, etc):

Site Conditions: Is location within a sensitive area (according to Rule 901e)? ☐ Y ☑ N If yes, attach evaluation.

Adjacent land use (cultivated, irrigated, dry land farming, industrial, residential, etc.): Dry land farming (not in production)

Soil type, if not previously identified on Form 2A or Federal Surface Use Plan:

Potential receptors (water wells within 1/4 mi, surface waters, etc.): Water well at 300'

Description of Impact (if previously provided, refer to that form or document):

Impacted Media (check):	Extent of Impact:	How Determined:
☑ Soils	Near well head and former tank location	Inspection Document 667100032
☐ Vegetation		
☐ Groundwater		
☐ Surface Water		

REMEDIATION WORKPLAN

Describe initial action taken (if previously provided, refer to that form or document):

29580lb of contaminated soil was removed on 6-19-2012 (Tracking No. 200374644, Document No. 2485390) .

Describe how source is to be removed:

Contaminated soil will be removed using appropriate backhoe, based upon the depth of contamination as determined from the Site Investigation Work Plan (attached).

Describe how remediation of existing impacts is to be accomplished, including removal and disposal at an injection well or licensed facility, land treatment on site, removal of impacted groundwater, insitu bioremediation, burning of oily vegetation, etc.:

Hauling to liscensed land fill (Twin Enviro in Milner).

Submit Page 2 with Page 1