

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
01/02/2014

Document Number:
663902597

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>335579</u>	<u>335579</u>	<u>LONGWORTH, MIKE</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: _____

Name of Operator: ENCANA OIL & GAS (USA) INC

Address: 370 17TH ST STE 1700

City: DENVER State: CO Zip: 80202-

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
YOKLEY, BILL		bill.yokley@state.co.us	
Insp., General	970-285-2665	cogcc.inspections@encana.com	

Compliance Summary:

QtrQtr: SWNW Sec: 19 Twp: 5S Range: 95W

Inspector Comment:

No evidence of AL well 045-14796

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
29	WELL	PR	01/02/2007	GW	045-11674	N. PARACHUTE EF05D E19 595	PR
282300	WELL	PR	03/31/2008	GW	045-11711	N. PARACHUTE E02C-24 E19 595	PR
282301	WELL	PR	12/29/2005	GW	045-11712	N. PARACHUTE EF05C E19 595	PR
282302	WELL	PR	03/27/2008	GW	045-11713	N. PARACHUTE EF02D-24 E19 59	PR
282303	WELL	PR	02/25/2008	GW	045-11714	N.PARACHUTE EF05B-19 E19 59	PR
282304	WELL	PR	01/12/2007	GW	045-11715	N.PARACHUTE EF09B E19 595	PR
282305	WELL	PR	01/02/2007	GW	045-11716	N.PARACHUTE EF09D E19 595	PR
282306	WELL	PR	01/04/2007	GW	045-11717	N. PARACHUTE EFO5B E19 595	PR
291668	WELL	PR	05/27/2008	GW	045-14492	N. PARACHUTE EF09A-24 E19 59	PR
291669	WELL	PR	07/06/2008	GW	045-14491	N. PARACHUTE EF10A-24E19 595	PR
291670	WELL	PR	06/07/2008	GW	045-14490	N. PARACHUTE EF10B-24E19 595	PR

291671	WELL	PR	07/31/2007	GW	045-14489	N. PARACHUTE EF10C-24E19 595	PR	<input type="checkbox"/>
291672	WELL	PR	07/31/2007	GW	045-14488	N.PARACHUTE EF08C-24 E19 59	PR	<input type="checkbox"/>
291674	WELL	PR	07/31/2007	GW	045-14478	N. PARACHUTE EF10D-24E19 595	PR	<input type="checkbox"/>
291675	WELL	PR	11/16/2008	GW	045-14479	N.PARACHUTE EF02B-24 E19 59	PR	<input type="checkbox"/>
291676	WELL	PR	11/06/2008	GW	045-14480	N.PARACHUTE EF08B-24 E19 59	PR	<input type="checkbox"/>
291677	WELL	PR	06/21/2008	GW	045-14481	N.PARACHUTE EF08D-24 E19 59	PR	<input type="checkbox"/>
291681	WELL	PR	02/01/2011	GW	045-14486	N.PARACHUTE EF07B-24 E19 59	PR	<input type="checkbox"/>
291682	WELL	PR	11/13/2008	GW	045-14487	N.PARACHUTE EF07A-24 E19 59	PR	<input type="checkbox"/>
291683	WELL	PR	11/09/2008	GW	045-14485	N. PARACHUTE EF01D-24 E19 59	PR	<input type="checkbox"/>
291684	WELL	PR	11/17/2008	GW	045-14484	N. PARACHUTE EF01B-24 E19 59	PR	<input type="checkbox"/>
291685	WELL	PR	07/03/2008	GW	045-14483	N. PARACHUTE EF07D-24E19 595	PR	<input type="checkbox"/>
291686	WELL	PR	11/07/2008	GW	045-14482	N. PARACHUTE EF07C-24 E19 59	PR	<input type="checkbox"/>
292401	WELL	PR	11/01/2008	GW	045-14719	N. PARACHUTE EF08A-24 E19 59	PR	<input type="checkbox"/>
292449	WELL	PR	11/07/2008	GW	045-14725	N. PARACHUTE EF 16A-24 E19 5	PR	<input type="checkbox"/>
292450	WELL	PR	11/07/2008	GW	045-14724	N. PARACHUTE EF09C-24 E19 59	PR	<input type="checkbox"/>
292886	WELL	AL	02/27/2009	LO	045-14796	N. PARACHUTE EF504D-19 E19 5	AL	<input checked="" type="checkbox"/>
293205	WELL	PR	11/20/2008	GW	045-14924	N.PARACHUTE EF02A-24 E19 59	PR	<input type="checkbox"/>
293206	WELL	PR	11/20/2008	GW	045-14925	N.PARACHUTE EF01A-24 E19 59	PR	<input type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 335579

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/U/V: _____ **Comment:**

CA: **Date:** _____

Wildlife BMPs:

S/U/V: _____ **Comment:**

CA: **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 292886 Type: WELL API Number: 045-14796 Status: AL Insp. Status: AL

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment:
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment:

1003a. Debris removed? _____ CM _____
 CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT