

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

01/02/2014

Document Number:

600000578

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 246458 | 327167 | JOHNSON, RANDELL | <input type="checkbox"/> | |

Operator Information:

OGCC Operator Number:

Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| | | | |
|----------------|-------|---------------------------|---------|
| Contact Name | Phone | Email | Comment |
| Fogel, Heather | | hfogel@nobleenergyinc.com | |

Compliance Summary:QtrQtr: NESW Sec: 22 Twp: 1N Range: 66W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 07/10/2003 | 200041763 | PR | PR | Satisfactory | | Pass | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 246458 | WELL | PR | 04/12/1993 | GW | 123-14255 | MADRIGAL 2-22 | SI | <input checked="" type="checkbox"/> |

Equipment:**Location Inventory**

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Signs/Marker: | | | | |
|----------------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| BATTERY | Satisfactory | | | |
| TANK LABELS/PLACARDS | Satisfactory | | | |
| WELLHEAD | Satisfactory | | | |

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Inspector Name: JOHNSON, RANDELL

| | |
|--------------------|--|
| Comment: | |
| Corrective Action: | |

| | | | | |
|--|------|--------|-------------------|---------|
| Spills: | | | | |
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| | | | | |
|------------------|-----------------------------|---------|-------------------|---------|
| Fencing/: | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD | Satisfactory | | | |

| | | | | | |
|-----------------------------|---|-----------------------------|---------|-------------------|---------|
| Equipment: | | | | | |
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Horizontal Heated Separator | 1 | Satisfactory | | | |
| Plunger Lift | 1 | Satisfactory | | | |
| Gas Meter Run | 1 | Satisfactory | | | |
| Emission Control Device | 1 | Satisfactory | | | |

| | | | | | |
|---|--------------|-----------|-------------|-----------------------|--|
| Facilities: <input type="checkbox"/> New Tank Tank ID: _____ | | | | | |
| Contents | # | Capacity | Type | SE GPS | |
| PRODUCED WATER | 1 | <100 BBLS | BV CONCRETE | 40.040620,-104.768250 | |
| S/U/V: | Satisfactory | Comment: | | | |
| Corrective Action: | | | | Corrective Date: | |

| | |
|------------------------|----------|
| Paint | |
| Condition | Adequate |
| Other (Content) _____ | |
| Other (Capacity) _____ | |
| Other (Type) _____ | |

| | | | | |
|-------------------|----------|---------------------|---------------------|-----------------|
| Berms | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficent | Base Sufficient | Adequate |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

| | | | | | |
|--------------------------|-----------------------------|-----------------------------------|---------------------|------------------------|--|
| Facilities: | | <input type="checkbox"/> New Tank | | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS | |
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | 40.040620,-104.768250 | |
| S/U/V: | Satisfactory | | Comment: _____ | | |
| Corrective Action: _____ | | | | Corrective Date: _____ | |
| Paint | | | | | |
| Condition | Adequate | | | | |
| Other (Content) _____ | | | | | |
| Other (Capacity) _____ | | | | | |
| Other (Type) _____ | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |
| Venting: | | | | | |
| Yes/No | | Comment | | | |
| NO | | | | | |
| Flaring: | | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date | |
| | | | | | |

Predrill

Location ID: 246458

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 246458 Type: WELL API Number: 123-14255 Status: PR Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

S/V: _____ CA Date: _____

CA: _____

Comment: Producing intermittently

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: JOHNSON, RANDELL

| | | | |
|---|--|------------------------------|------------|
| Comment: <input style="width:700px" type="text"/> | | | |
| Corrective Action: _____ | | Date: _____ | |
| Reportable: _____ | GPS: Lat _____ | Long _____ | |
| Proximity to Surface Water: _____ | | Depth to Ground Water: _____ | |
| Water Well: | | | |
| | | Lat _____ | Long _____ |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ | |
| Field Parameters: | | | |
| <input style="width:300px" type="text"/> | | | |
| Sample Location: <input style="width:400px" type="text"/> | | | |
| Emission Control Burner (ECB): _____ | | | |
| Comment: _____ | | | |
| Pilot: _____ | Wildlife Protection Devices (fired vessels): _____ | | |

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment:

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? Pass CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Inspector Name: JOHNSON, RANDELL

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT