

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:

01/02/2014

Document Number:

671100634

Overall Inspection:

**Unsatisfactory****FIELD INSPECTION FORM**

|                     |             |        |                 |                          |             |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection       | 2A Doc Num: |
|                     | 202067      | 319973 | MONTOYA, JOHN   | <input type="checkbox"/> |             |

**Operator Information:**

OGCC Operator Number:

Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED**Contact Information:**

| Contact Name   | Phone        | Email                 | Comment       |
|----------------|--------------|-----------------------|---------------|
| Fritzler, Gene | 970-768-0845 | gfritzler@bresnan.net | left msg 9/21 |

**Compliance Summary:**QtrQtr: SESW Sec: 1 Twp: 1S Range: 58W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 09/18/2012 | 663400842 | PR         | PR          | Unsatisfactory               | P        |                | No              |
| 12/12/1997 | 500132123 | ID         | TA          |                              |          | Fail           | No              |

**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 202067      | WELL | PR     | 09/01/2012  | OW         | 001-07472 | SIMPSON A 12  | PR          | <input checked="" type="checkbox"/> |

**Equipment:**Location Inventory

|                             |                        |                     |                         |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____     | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____  | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____      | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____      | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location****Signs/Marker:**

| Type     | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|----------|-----------------------------|---------|-------------------|---------|
| WELLHEAD | Satisfactory                |         |                   |         |

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: MONTOYA, JOHN

Corrective Action:

| <b>Spills:</b> |          |           |   |            |
|----------------|----------|-----------|---|------------|
| Type           | Area     | Volume    | Corrective action                                     | CA Date    |
| Crude Oil      | WELLHEAD | <= 5 bbls | soiled dirt needs cleaned up around wellhead and unit | 02/02/2014 |

☒ Multiple Spills and Releases?

| <b>Fencing/:</b> |                             |         |                   |         |
|------------------|-----------------------------|---------|-------------------|---------|
| Type             | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| PUMP JACK        | Satisfactory                |         |                   |         |

| <b>Equipment:</b>  |   |                             |         |                   |         |
|--------------------|---|-----------------------------|---------|-------------------|---------|
| Type               | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Deadman # & Marked | 4 | Satisfactory                |         |                   |         |
| Pump Jack          | 1 | Satisfactory                |         |                   |         |

| <b>Venting:</b> |         |  |
|-----------------|---------|--|
| Yes/No          | Comment |  |
|                 |         |  |

| <b>Flaring:</b> |                             |         |                   |         |
|-----------------|-----------------------------|---------|-------------------|---------|
| Type            | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|                 |                             |         |                   |         |

**Predrill**

Location ID: 202067

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/U/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 202067 Type: WELL API Number: 001-07472 Status: PR Insp. Status: PR

**Producing Well**

Comment: pr

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_

Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Inspector Name: MONTOYA, JOHN

Comment:

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started:

Date Final Reclamation Completed:

Final Land Use:

Reminder:

Comment:

Well plugged

Pit mouse/rat holes, cellars backfilled

Debris removed

No disturbance /Location never built

Access Roads Regraded

Contoured

Culverts removed

Gravel removed

Location and associated production facilities reclaimed

Locations, facilities, roads, recontoured

Compaction alleviation

Dust and erosion control

Non cropland: Revegetated 80%

Cropland: perennial forage

Weeds present

Subsidence

Comment:

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs     | BMP Maintenance      | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs        | Chemical BMP Maintenance | Comment              |
|----------------------|----------------------|-------------------------|-----------------------|----------------------|--------------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/>    | <input type="text"/>  | <input type="text"/> | <input type="text"/>     | <input type="text"/> |

S/U/V:

Corrective Date:

Comment:

CA:

**Pits:** ☐ NO SURFACE INDICATION OF PIT