

Inspector Name: Sherman, Susan

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

01/03/2014

Document Number:

673700676

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection
	237268	317216	Sherman, Susan	<input type="checkbox"/> 2A Doc Num: _____

Operator Information:

OGCC Operator Number: _____

Name of Operator: STELBAR OIL CORP INCAddress: 1625 N WATERFRONT PKWY #200City: WICHITA State: KS Zip: 67206-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Mendenhall, Roscoe	316-264-8378 off	roscoe@stelbar.com	

Compliance Summary:QtrQtr: NWSW Sec: 35 Twp: 2S Range: 50W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
104575	PIT		09/23/1999		-	SMALL 1-35	<input type="checkbox"/>
117751	PIT		09/23/1999		-	SMALL 1-35	<input type="checkbox"/>
237268	WELL	PR	12/16/1996	GW	121-09769	SMALL, R. 1-35	PR <input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	Deep sand.		

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Inspector Name: Sherman, Susan

Comment:

Corrective Action:

Good Housekeeping:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WEEDS	Unsatisfactory	At wellhead.	Control.	05/01/2014

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	Barbed and pig wire.		
LOCATION	Satisfactory	Barbed and pig wire.		

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Veritcal Heater Treater	1	Satisfactory			
Gas Meter Run	3	Satisfactory			

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 237268

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 237268 Type: WELL API Number: 121-09769 Status: PR Insp. Status: PR

Producing WellComment: PR
Sept 2013 last reported**Environmental****Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Inspector Name: Sherman, Susan

Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: **Rangeland**

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

Inspector Name: Sherman, Susan

1003 f. Weeds Noxious weeds? _____

Comment: **weeds**

Overall Interim Reclamation **Fail**

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass	Compaction	Pass	MHSP	Fail	

S/U/V: **Unsatisfactory**

Corrective Date: **01/24/2014**

Comment: **Chemical containers need stormwater protection (see attached photos).**

CA: **Install BMPs.**

Pits: ☐ NO SURFACE INDICATION OF PIT

Inspector Name: Sherman, Susan

Pit Type: <u>Evaporation</u>	Lined: <u>NO</u>	Pit ID: _____	Lat: _____	Long: _____
Lining:				
Liner Type: _____	Liner Condition: _____			
Comment: _____				
Fencing:				
Fencing Type: _____	Fencing Condition: _____			
Comment: _____				
Netting:				
Netting Type: _____	Netting Condition: _____			
Comment: _____				
Anchor Trench Present: _____	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: _____		
Pit (S/U/V): <u>Satisfactory</u>	Comment: <u>Owner is Sand Hills Society on pit permit.</u>			
Corrective Action: _____				Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673700720	Stelbar R. Small #1-35 Evap pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3256991
673700721	Stelbar R. Small #1-35 Evap pit2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3256992
673700722	Stelbar R. Small #1-35 Evap pit3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3256993
673700723	Stelbar R. Small #1-35 Meter houses	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3256994
673700724	Stelbar R. Small #1-35 Meter pipeline	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3256995
673700725	Stelbar R. Small #1-35 N Meter house	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3256996
673700726	Stelbar R. Small #1-35 Pipeline	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3256997
673700727	Stelbar R. Small #1-35 Sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3256998
673700728	Stelbar R. Small #1-35 Well container	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3256999
673700729	Stelbar R. Small #1-35 Well equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3257000
673700731	Stelbar R. Small #1-35 Well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3257001
673700732	Stelbar R. Small #1-35 Wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3257002
673700746	Stelbar R. Small #1-35 Container	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3257003