

FORM INSP <small>Rev 05/11</small>	State of Colorado				DE	ET	OE	ES	
	Oil and Gas Conservation Commission				Inspection Date: <u>01/05/2014</u>				
<small>1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109</small>				Document Number: <u>668500332</u>					
FIELD INSPECTION FORM				Overall Inspection: <u>Satisfactory</u>					
Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection					
	324454	324454	Baroumand, Soraya	<input type="checkbox"/>	2A Doc Num: _____				

Operator Information:

OGCC Operator Number: _____

Name of Operator: ANTERO RESOURCES PICEANCE LLC

Address: 1625 17TH ST STE 300

City: DENVER State: CO Zip: 80202

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Honeycutt, Matt		mhoneycutt@ursaresources.com	
Smith, Cody		csmith@ursaresources.com	
Shauna Dematte		sdemattee@anteroresources.com	
RAMOS, MARTHA		martha.ramos@state.co.us	
Bleil, Rob	(720) 508-8350	rbleil@ursaresources.com	Regulatory & Environmental Manager
Redican, Shauna	(303) 357-6820	sredican@anteroresources.com	Permit Representative

Compliance Summary:

QtrQtr: SENW Sec: 11 Twp: 6S Range: 93W

Inspector Comment:

Bond Release Inspection: No wells were ever drilled for this location. Location is within a multi-use industrial/construction storage lot which existed prior to Applications for Permit to Drill. Refer to ending comments section of report for details.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
301603	WELL	AL	10/02/2012	LO	045-18207	WSDC B16	AL	X
412099	WELL	AL	10/02/2012	LO	045-18427	WSDC B17	AL	X
412100	WELL	AL	10/03/2012	LO	045-18428	WSDC B11	AL	X
412101	WELL	AL	10/03/2012	LO	045-18429	WSDC B2	AL	X
412107	WELL	AL	10/03/2012	LO	045-18430	WSDC B4	AL	X
412108	WELL	AL	10/03/2012	LO	045-18431	WSDC B3	AL	X
412109	WELL	AL	10/02/2012	LO	045-18432	WSDC B14	AL	X
412110	WELL	AL	10/03/2012	LO	045-18433	WSDC B5	AL	X
412111	WELL	AL	10/02/2012	LO	045-18434	WSDC B12	AL	X
412112	WELL	AL	10/03/2012	LO	045-18435	WSDC B7	AL	X
412113	WELL	AL	10/03/2012	LO	045-18436	WSDC B6	AL	X
412114	WELL	AL	10/02/2012	LO	045-18437	WSDC B13	AL	X

Equipment:		<u>Location Inventory</u>	
Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 324454

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 301603 Type: WELL API Number: 045-18207 Status: AL Insp. Status: AL

Facility ID: 412099 Type: WELL API Number: 045-18427 Status: AL Insp. Status: AL

Facility ID: 412100 Type: WELL API Number: 045-18428 Status: AL Insp. Status: AL

Facility ID: 412101 Type: WELL API Number: 045-18429 Status: AL Insp. Status: AL

Facility ID: 412107 Type: WELL API Number: 045-18430 Status: AL Insp. Status: AL

Facility ID: 412108 Type: WELL API Number: 045-18431 Status: AL Insp. Status: AL

Facility ID: <u>412109</u>	Type: <u>WELL</u>	API Number: <u>045-18432</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>412110</u>	Type: <u>WELL</u>	API Number: <u>045-18433</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>412111</u>	Type: <u>WELL</u>	API Number: <u>045-18434</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>412112</u>	Type: <u>WELL</u>	API Number: <u>045-18435</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>412113</u>	Type: <u>WELL</u>	API Number: <u>045-18436</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>412114</u>	Type: <u>WELL</u>	API Number: <u>045-18437</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment:
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment:
 1003a. Debris removed? _____ CM _____ CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____ CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____ CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: **Industrial/commercial land uses of subject site and areas to the south. Rural residential community to the west, north and east.**

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built Pass

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: **Location never developed for oil and gas drilling and no wells were drilled. Site is occupied by an industrial/commercial storage yard.**

Corrective Action: _____ Date _____

Overall Final Reclamation Pass Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Inspector Name: Baroumand, Soraya

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>Passing Bond Release Inspection. No wells were drilled and the location was not built to serve as a well pad for drilling. Approved Sundry (Doc #2172121) on file indicating Antero has abandoned APDs of undrilled location and that the "pad" was not constructed.</p> <p>Field observations indicate that the subject location is within a fenced industrial/construction storage lot which houses equipment and supplies related to oil/gas, construction and building operations. Reviews of aerial images indicate this use existing prior to mid 2009.</p> <p>Archived documents in database also demonstrate the pre-existence of the storage facility prior to APDs; such as: Location Photos taken in July 2008 (Doc # 1827400), Surface Agreement (Doc# 1827387), Notice of Intent to Conduct Surface Operations (Doc#1827386), and Well Location Plat (Doc #1827390).</p>	baroumas	01/06/2014