

Inspector Name: QUINT, CRAIG

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

01/07/2014

Document Number:

668601933

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection
	207335	321575	QUINT, CRAIG	<input type="checkbox"/> 2A Doc Num: _____

Operator Information:

OGCC Operator Number: _____

Name of Operator: MULL DRILLING COMPANY INCAddress: 1700 N WATERFRONT PKWY B#1200City: WICHITA State: KS Zip: 67206-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Smalley, Carl	719-767-8805 off	csmalley@mulldrilling.com	719-342-1812 cell

Compliance Summary:QtrQtr: NWSW Sec: 3 Twp: 14S Range: 49W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/20/2011	663900252	PR	PR	Satisfactory	P		No
05/03/2010	200246040	PR	PR	Satisfactory			No
04/06/2010	200241615	PR	PR	Unsatisfactory			Yes
12/05/2006	200100534	PR	PR	Satisfactory		Pass	No
12/13/1999	500138426	PR	PR			Pass	No
12/09/1997	500138425	PR	PR			Pass	No
04/19/1996	500138424	PR	PR			Pass	No
11/18/1994	500138423		PR				

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115012	PIT		09/23/1999		-	MCCORMICK	<input type="checkbox"/>
207335	WELL	PR	03/18/2008	OW	017-06270	MULL UNIT 17	PR <input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	GRAVEL ROAD THROUGH PASTURE		

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	LEASE SIGN BY UNIT		
CONTAINERS	Satisfactory	STICKERS		

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	STEEL PANELS AROUND ALL WELLHEAD EQUIPMENT		

Facilities:☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
			CENTRALIZED BATTERY	38.848360,-102.893960

S/U/V: Satisfactory Comment: MUSF #3 CENTRAL BATTERY F/(MU #15, 17, 18, 19, 20) 3950' SOUTH WEST.

Corrective Action: _____ Corrective Date: _____

Paint

Condition _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action _____ Corrective Date _____

Comment _____

Venting:

Yes/No	Comment
NO	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 207335

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 207335 Type: WELL API Number: 017-06270 Status: PR Insp. Status: PR

Producing Well

Comment: PRODUCING, MUSF #3 CENTRAL BATTERY F/(MU #15, 17, 18, 19, 20) 3950' SOUTH WEST @ 38.848360, -102.893960

Environmental**Spills/Releases:**

Inspector Name: QUINT, CRAIG

Type of Spill: _____	Description: _____	Estimated Spill Volume: _____
Comment: _____		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____		Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____	Owner Name: _____	GPS : _____	Lat _____	Long _____
------------------------	-------------------	-------------	-----------	------------

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Inspector Name: QUINT, CRAIG

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	MHSP	Pass	

S/U/V: Satisfactory _____

Corrective Date: _____

Comment: **CONTAINMENTS HAVE BEEN INSTALLED SINCE LAST INSPECTION.**

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT