

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:
400412520

Date Received:
05/21/2013

SUNDRY NOTICE

Submit a signed original. This form is to be used for general, technical and environmental sundry information. For proposed or completed operations, describe in full in Comments or provide as an attachment. Identify Well by API Number; identify Oil and Gas Location by Location ID Number; identify other Facility by Facility ID Number.

OGCC Operator Number: <u>100185</u> Contact Name <u>Kathy Vertiz</u>				Complete the Attachment Checklist OP OGCC		
Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u>		Phone: <u>(970) 285-2626</u>				
Address: <u>370 17TH ST STE 1700</u>		Fax: <u>()</u>				
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202-5632</u>	Email: <u>kathy.vertiz@encana.com</u>			
API Number : 05- <u>103</u> <u>07030</u> <u>00</u> OGCC Facility ID Number: <u>229375</u>				Survey Plat		
Well/Facility Name: <u>DRAGON TRAIL UNIT</u>		Well/Facility Number: <u>1016</u>		Directional Survey		
Location QtrQtr: <u>NWNW</u>	Section: <u>33</u>	Township: <u>2S</u>	Range: <u>102W</u>	Meridian: <u>6</u>	Srfc Eqpmt Diagram	
County: <u>RIO BLANCO</u>		Field Name: <u>DRAGON TRAIL</u>		Technical Info Page		
Federal, Indian or State Lease Number: <u>44954</u>				Other		

CHANGE OF LOCATION OR AS BUILT GPS REPORT

- ☐ Change of Location * ☐ As-Built GPS Location Report ☐ As-Built GPS Location Report with Survey

* Well location change requires new plat. A substantive surface location change may require new Form 2A.

SURFACE LOCATION GPS DATA Data must be provided for Change of Surface Location and As Built Reports.

Latitude _____ PDOP Reading _____ Date of Measurement _____
Longitude _____ GPS Instrument Operator's Name _____

LOCATION CHANGE (all measurements in Feet)

Well will be: (Vertical, Directional, Horizontal)

Change of **Surface** Footage **From** Exterior Section Lines:

Change of **Surface** Footage **To** Exterior Section Lines:

Current Surface Location From	QtrQtr	NWNW	Sec	33
--------------------------------------	--------	------	-----	----

New **Surface** Location To QtrQtr Sec

Change of **Top of Productive Zone** Footage **From** Exterior Section Lines:

Change of **Top of Productive Zone** Footage To Exterior Section Lines:

Current	Top of Productive Zone Location	From	Sec

New **Top of Productive Zone** Location To Sec

Change of **Bottomhole** Footage **From** Exterior Section Lines:

Change of **Bottomhole** Footage To Exterior Section Lines:

Current **Bottomhole** Location Sec Twp

New **Bottomhole** Location Sec Twp

Is location in High Density Area?

Distance, in feet, to nearest building _____, public road: _____, above ground utility: _____, railroad: _____,

property line: _____, lease line: _____, well in same formation: _____

Ground Elevation feet Surface owner consultation date

Survey Plat		
Directional Survey		
Srfc Eqpmt Diagram		
Technical Info Page		
Other		

CHANGE OR ADD OBJECTIVE FORMATION AND/OR SPACING UNIT

<u>Objective Formation</u>	<u>Formation Code</u>	<u>Spacing Order Number</u>	<u>Unit Acreage</u>	<u>Unit Configuration</u>

OTHER CHANGES

☐ **REMOVE FROM SURFACE BOND** Signed surface use agreement is a required attachment

☐ **CHANGE OF WELL, FACILITY OR OIL & GAS LOCATION NAME OR NUMBER**

From: Name DRAGON TRAIL UNIT Number 1016 Effective Date: _____

To: Name _____ Number _____

☐ **ABANDON PERMIT: Permit can only be abandoned if the permitted operation has NOT been conducted. Field inspection will be conducted to verify site status.**

☐ WELL: Abandon Application for Permit-to-Drill (Form2) – Well API Number _____ has not been drilled.

☐ PIT: Abandon Earthen Pit Permit (Form 15) – COGCC Pit Facility ID Number _____ has not been constructed (Permitted and constructed pit requires closure per Rule 905)

☐ CENTRALIZED E&P WASTE MANAGEMENT FACILITY: Abandon Centralized E&P Waste Management Facility Permit (Form 28) – Facility ID Number _____ has not been constructed (Constructed facility requires closure per Rule 908)

OIL & GAS LOCATION ID Number: _____

☐ Abandon Oil & Gas Location Assessment (Form 2A) – Location has not been constructed and site will not be used in the future.

☐ Keep Oil & Gas Location Assessment (Form 2A) active until expiration date. This site will be used in the future.

Surface disturbance from Oil and Gas Operations must be reclaimed per Rule 1003 and Rule 1004.

☐ **REQUEST FOR CONFIDENTIAL STATUS**

☐ **DIGITAL WELL LOG UPLOAD**

☐ **DOCUMENTS SUBMITTED** Purpose of Submission: _____

RECLAMATION**INTERIM RECLAMATION**

☐ Interim Reclamation will commence approximately _____

Per Rule 1003.e.(3) operator shall submit Sundry Notice reporting interim reclamation is complete and site is ready for inspection when vegetation reaches 80% coverage.

☐ Interim reclamation complete, site ready for inspection.

Per Rule 1003.e(3) describe interim reclamation procedure in Comments below or provide as an attachment and attach required location photographs.

Field inspection will be conducted to document Rule 1003.e. compliance

FINAL RECLAMATION

☐ Final Reclamation will commence approximately _____

Per Rule 1004.c.(4) operator shall submit Sundry Notice reporting final reclamation is complete and site is ready for inspection when vegetation reaches 80% coverage.

☒ Final reclamation complete, site ready for inspection. Per Rule 1004.c(4) describe final reclamation procedure in Comments below or provide as an attachment.

Field inspection will be conducted to document Rule 1004.c. compliance

Comments:

Please see attached reclamation details.

Also attached is a copy of the 3160-5 Sundry Notice that the Meeker BLM office approved the Final Reclamation on 3/14/2013.

Well Plugged: 09/05/2007 by Encana Oil and Gas

Final Reclamation/Abandoned Location:

Date Final Reclamation Started: 10/27/2007

Date Final Reclamation Completed: 06/01/2010

Date Seeded: 10/27/2007 Seed tags attached: Yes

Final Land Use: Rangeland

Pit mouse/rat holes, cellars backfilled: Yes

Debris removed: Yes

No disturbance/Location was never built: N/A

Access Roads:

Regraded: Yes

Contoured: Yes

Culverts Removed: Yes

Gravel Removed: Yes

Location and associated production facilities reclaimed

This location is on Non Crop land with reclamation done per Rule 1004, and inspected by Encana.

Reviewed and evaluated again 06/01/2010

Locations and facilities recountoured: Yes

Flowline/Pipelines were abandoned per Rule 1103

Compaction alleviation: Yes

Dust and erosion control: Yes

Non cropland-revegetated 80%: Presently 80 %

Cropland-perennial Forage: NA

Weeds Present: No

Subsidence (cropland): NA

Final Reclamation procedure: This location is ready for inspection New Surface Reclam Inspection (SR)

Notes:

There is an active pipeline, with risers and grasshoppers, that passes through the location that services other wells.

ENGINEERING AND ENVIRONMENTAL WORK

☐ NOTICE OF CONTINUED TEMPORARILY ABANDONED STATUS

Indicate why the well is temporarily abandoned and describe future plans for utilization in the COMMENTS box below or provide as an attachment, as required by Rule 319.b.(3).

Date well temporarily abandoned _____ Has Production Equipment been removed from site? _____

Mechanical Integrity Test (MIT) required if shut in longer than 2 years. Date of last MIT _____

☐ SPUD DATE: _____

TECHNICAL ENGINEERING AND ENVIRONMENTAL WORK

Details of work must be described in full in the COMMENTS below or provided as an attachment.

☐ NOTICE OF INTENT Approximate Start Date _____

☐ REPORT OF WORK DONE Date Work Completed _____

- | | | |
|--|---|--|
| <input type="checkbox"/> Intent to Recomplete (Form 2 also required) | <input type="checkbox"/> Request to Vent or Flare | <input type="checkbox"/> E&P Waste Management Plan |
| <input type="checkbox"/> Change Drilling Plan | <input type="checkbox"/> Repair Well | <input type="checkbox"/> Beneficial Reuse of E&P Waste |
| <input type="checkbox"/> Gross Interval Change | <input type="checkbox"/> Rule 502 variance requested. Must provide detailed info regarding request. | |
| <input type="checkbox"/> Other _____ | <input type="checkbox"/> Status Update/Change of Remediation Plans for Spills and Releases | |

COMMENTS:

CASING AND CEMENTING CHANGES

Casing Type	Size	Of	/	Hole	Size	Of	/	Casing	Wt/Ft	Csg/LinTop	Setting Depth	Sacks of Cement	Cement Bottom	Cement Top

H2S REPORTING

Data Fields in this section are intended to document Sample and Location Data associated with the collection of a Gas Sample that is submitted for Laboratory Analysis.

Gas Analysis Report must be attached.

H2S Concentration: _____ in ppm (parts per million) Date of Measurement or Sample Collection _____

Description of Sample Point:

Absolute Open Flow Potential _____ in CFPD (cubic feet per day)

Description of Release Potential and Duration (If flow is not open to the atmosphere, identify the duration in which the container or pipeline would likely be opened for servicing operations.):

Distance to nearest occupied residence, school, church, park, school bus stop, place of business, or other areas where the public could reasonably be expected to frequent: _____

Distance to nearest Federal, State, County, or municipal road or highway owned and principally maintained for public

use: _____

COMMENTS:

Best Management Practices

No BMP/COA Type

Description

------	------

Operator Comments:

--

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Kathy Vertiz

Title: Lead, Surface
Management

Email: kathy.vertiz@encana.com

Date: 5/21/2013

Based on the information provided herein, this Sundry Notice (Form 4) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Baroumand, Soraya

Date: 1/14/2014

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

------	------

General Comments

User Group

Comment

Comment Date

------	------	------

Total: 0 comment(s)

Attachment Check List

Att Doc Num

Name

400412520	FORM 4 SUBMITTED
400421486	BLM SUNDRY
400421502	FINAL RECLAMATION PROCEDURE

Total Attach: 3 Files